WEAR CONTAMINATION **FLUID CONDITION** **NORMAL NORMAL NORMAL**

[HERC RENTALS] **VOLVO A30G 753394**

Rear Axle

VOLVO PREMIUM GEAR OIL 85	W-140 GL-	o (GAL)		.,		
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Resample at the next service interval to monitor.	Sample Number		Client Info		VCP449699		
	Sample Date		Client Info		20 May 2024		
	Machine Age	hrs	Client Info		1120		
	Oil Age	hrs	Client Info		0		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		Not Changd		
	Filter Changed		Client Info		Not Changd		
	Sample Status				NORMAL		
WEAR	Iron	ppm	ASTM D5185m	>900	0		
All component wear rates are normal.	Chromium	ppm	ASTM D5185m	>20	0		
	Nickel	ppm	ASTM D5185m		0		
	Titanium	ppm	ASTM D5185m		0		
	Silver	ppm	ASTM D5185m		0		
	Aluminum	ppm	ASTM D5185m	>30	0		
	Lead	ppm	ASTM D5185m	>50	0		
	Copper	ppm	ASTM D5185m	>150	0		
	Tin	ppm	ASTM D5185m	>20	0		
	Vanadium	ppm	ASTM D5185m		0		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION	Silicon	ppm	ASTM D5185m	<u>~50</u>	<1		
There is no indication of any contamination in the oil.	Potassium	ppm	ASTM D5185m		0		
	Water	PPIII		>0.2	NEG		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>0.2	NEG		
FLUID CONDITION	Cadium		ACTM DE10Em				
	Sodium Boron	ppm	ASTM D5185m ASTM D5185m	111	0 229		
The condition of the oil is acceptable for the time in service.	Barium	ppm	ASTM D5185m		0		
	Molybdenum	ppm	ASTM D5185m		0		
	Manganese	ppm	ASTM D5185m		0		
	Magnesium	ppm	ASTM D5185m		7		
	Calcium	ppm	ASTM D5185m		149		
	Phosphorus	ppm	ASTM D5185m	920	1116		
	Zinc	ppm	ASTM D5185m		55		
	ZITIC	PP					
	Sulfur	ppm		20179	34382		





Certificate L2367

Laboratory Sample No. Lab Number : 06194378

Test Package : MOB 1

: VCP449699 Unique Number : 11056501

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received **Tested**

: 29 May 2024 : 31 May 2024 Diagnosed

: 31 May 2024 - Wes Davis

ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC 8418 PALM RIVER ROAD

TAMPA, FL US 33619

Contact: KENNY HANEY khaney@flaglerce.com

T: (813)630-0077 F: (813)630-2233

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)