

[HERC] WOLVO L70H 623590 Component Diesel Engine

VOLVO ULTRA DIESEL ENGINE OIL 15W40 VDS-3 (--- GAL)

VOLVO ULTRA DILGLE LINGINE OIL 15VV40 VD3-5 (GAL)							
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Resample at the next service interval to monitor.	Sample Number		Client Info		VCP454978		
	Sample Date		Client Info		02 May 2024		
	Machine Age	hrs	Client Info		2359		
	Oil Age	hrs	Client Info		0		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		Changed		
	Filter Changed		Client Info		Changed		
	Sample Status				NORMAL		
					_		
WEAR All component wear rates are normal.	Iron	ppm	ASTM D5185m		2		
	Chromium	ppm	ASTM D5185m		<1		
	Nickel	ppm	ASTM D5185m	>10	<1		
	Titanium	ppm	ASTM D5185m		<1		
	Silver	ppm	ASTM D5185m		0		
	Aluminum	ppm	ASTM D5185m		4		
	Lead	ppm	ASTM D5185m		0		
	Copper	ppm	ASTM D5185m		<1		
	Tin	ppm	ASTM D5185m	>10	<1		
	Vanadium	ppm	ASTM D5185m		<1		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION	Silicon			. 00	E		
CONTAMINATION		ppm	ASTM D5185m		5 2		
There is no indication of any contamination in the oil.	Potassium	ppm	ASTM D5185m				
	Fuel		WC Method	>6.0	<1.0		
	Water		WC Method WC Method	>0.1	NEG		
	Glycol Soot %	%		. 0	NEG 0.1		
	Nitration		*ASTM D7844		5.0		
		Abs/cm	*ASTM D7624	>20			
	Sulfation	Abs/.1mm	*ASTM D7415		19.3		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>0.1	NEG		
FLUID CONDITION	Sodium	ppm	ASTM D5185m		1		
	Boron	ppm	ASTM D5185m	2.5	392		
The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.	Barium	ppm	ASTM D5185m		1		
	Molybdenum	ppm	ASTM D5185m		70		
	Manganese	ppm	ASTM D5185m		0		
	Magnesium	ppm	ASTM D5185m		378		
	Calcium	ppm	ASTM D5185m		1210		
	Phosphorus	ppm	ASTM D5185m		920		
	Zinc	ppm	ASTM D5185m		991		
	Sulfur	ppm	ASTM D5185m		2914		
	Oxidation	Abs/.1mm	*ASTM D310311		14.0		
		mg KOH/g	ASTM D2896		8.2		
	Visc @ 100°C	cSt			12.8		
		001	A0 I M D440	15.0	12.0		



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513 Sample No. : VCP454978 Received 8418 PALM RIVER ROAD : 30 May 2024 Lab Number : 06194956 Tested : 31 May 2024 TAMPA, FL Unique Number : 11057079 Diagnosed : 31 May 2024 - Don Baldridge US 33619 18 Test Package : MOB 1 (Additional Tests: TBN) Contact: KENNY HANEY Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369. khaney@flaglerce.com * - Denotes test methods that are outside of the ISO 17025 scope of accreditation. T: (813)630-0077 F: (813)630-2233 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

ÿ

Contact/Location: KENNY HANEY - VOLVO0093