**WEAR** CONTAMINATION **FLUID CONDITION**  **NORMAL NORMAL NORMAL** 

## [LKQ TAMPA] VOLVO L110H 632741

**Front Axle** 

ECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Resample at the next service interval to monitor.	Sample Number		Client Info		VCP437853		
	Sample Date		Client Info		23 Apr 2024		
	Machine Age	hrs	Client Info		1028		
	Oil Age	hrs	Client Info		0		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		Changed		
	Filter Changed		Client Info		N/A		
	Sample Status				NORMAL		
/EAR	Iron	nnm	ASTM D5185m	- 500	105		
LAN	Iron	ppm			125		
All component wear rates are normal.	Chromium Nickel	ppm	ASTM D5185m ASTM D5185m		2		
		ppm		>10	<1		
	Titanium Silver	ppm	ASTM D5185m ASTM D5185m		<1 0		
	Aluminum	ppm	ASTM D5185m	>30	1		
	Lead	ppm	ASTM D5185m		0		
	Copper	ppm	ASTM D5185m		1		
	Tin	ppm	ASTM D5185m		<1		
	Vanadium	ppm	ASTM D5185m	>20	<1		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
			Viouai		····		
ONTAMINATION	Silicon	ppm	ASTM D5185m	>50	30		
There is no indication of any contamination in the oil.	Potassium	ppm	ASTM D5185m	>20	3		
	Water		WC Method	>0.2	NEG		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>0.2	NEG		
LUID CONDITION	Sodium	nnm	ASTM D5185m		4		
	Boron	ppm		100	122		
The condition of the oil is acceptable for the time in service.	Barium	ppm	ASTM D5185m		<1		
	Molybdenum	ppm	ASTM D5185m		4		
	Manganese	ppm	ASTM D5185m	0	5		
	Magnesium	ppm	ASTM D5185m	0	13		
	Calcium		ASTM D5185m		3855		
	Phosphorus	ppm	ASTM D5185m		1309		
	Zinc	ppm	ASTM D5185m	1500	1590		
	Sulfur		ASTM D5185m		4254		
	Sullui	ppm	VO 11/1 D2 1021[]	0300	7234		





Certificate L2367

Laboratory Sample No.

: VCP437853 Lab Number : 06195767 Unique Number : 11057890 Test Package : MOB 1

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received **Tested** 

: 30 May 2024 : 31 May 2024 : 31 May 2024 - Wes Davis Diagnosed

ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC

8418 PALM RIVER ROAD TAMPA, FL US 33619

Contact: KENNY HANEY khaney@flaglerce.com

To discuss this sample report, contact Customer Service at 1-800-237-1369. \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T: (813)630-0077 F: (813)630-2233