

Machine Id

INGERSOLL RAND 21737

Compressor

INGERSOLL-RAND TECHTROL GOLD TL (35 GAL)

REC	OM	MEN	IDAT	ION
	U			

We recommend you service the filters on this component. Resample at the next service interval to monitor. We were unable to perform a particle count due to metal particles present in this sample.

	Test	UOM	Method	Limit/Abn	Current	History1	History2
at	Sample Number		Client Info		CCSI2011922		
	Sample Date		Client Info		25 May 2024		
	Machine Age	hrs	Client Info		5143		
	Oil Age	hrs	Client Info		5143		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		Not Changd		
	Filter Changed		Client Info		N/A		
	Sample Status				ABNORMAL		
	Iron	ppm	ASTM D5185m	>50	0		
	Chromium	ppm	ASTM D5185m	>10	0		
	Nickel	ppm	ASTM D5185m		0		
	Titanium	ppm	ASTM D5185m		0		
	Silver	ppm	ASTM D5185m		0		
	Aluminum	ppm	ASTM D5185m	>25	0		
	Lead	ppm	ASTM D5185m	>25	0		
	Copper	ppm	ASTM D5185m	>50	0		
	Tin	ppm	ASTM D5185m	>15	0		
	Vanadium	ppm	ASTM D5185m		0		
	White Metal	scalar	*Visual	NONE	A MODER		
	Yellow Metal	scalar	*Visual	NONE	NONE		
	Silicon		ASTM D5185m	>25	0		
	Potassium	ppm ppm	ASTM D5185m	>20	0		
	Water	ppin	WC Method	>0.1	NEG		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>0.1	NEG		
	Sodium	ppm	ASTM D5185m		<1		
	Boron	ppm	ASTM D5185m		0		
	Barium	ppm	ASTM D5185m		0		
	Molybdenum	ppm	ASTM D5185m		0		
	Manganese	ppm	ASTM D5185m		0		
	Magnesium	ppm	ASTM D5185m		0		
	Calcium	ppm	ASTM D5185m		<1		
	Phosphorus	ppm	ASTM D5185m		157		
	Zinc	ppm	ASTM D5185m		6		
	Sulfur	ppm	ASTM D5185m		23		
	Acid Number (AN)	mg KOH/g	ASTM D8045	0.25	0.82		
	. ,						

ASTM D445 37

Visc @ 40°C

cSt

WEAR

Moderate concentration of visible metal present. All component wear rates are normal.

CONTAMINATION


No other contaminants were detected in the oil.


FLUID CONDITION

The AN level is acceptable for this fluid. The condition of the oil is acceptable for the time in service.

Contact/Location: SHAWN CARTER - CAMBUF

38.8





Contact/Location: SHAWN CARTER - CAMBUF Page 2 of 2