

Iwaste MGMT] Machine Id VOLVO L60H 623294 Component Rear Axle Fluid VOLVO WB 102 (--- GAL)

RECOMMENDATION

Resample at the next service interval to monitor.

WEAR

All component wear rates are normal.

CONTAMINATION

There is no indication of any contamination in the oil.

FLUID CONDITION

The condition of the oil is acceptable for the time in service.

Test	UOM	Method	Limit/Abn	Current	History1	History2
Sample Number		Client Info		VCP443032	VCP437949	VCP430485
Sample Date		Client Info		10 Jun 2024	05 Apr 2024	14 Feb 2024
Machine Age	hrs	Client Info		2869	2319	2013
Oil Age	hrs	Client Info		0	2000	2013
Filter Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		Not Changd	Changed	Changed
Filter Changed		Client Info		Not Changd	Changed	Changed
Sample Status				NORMAL	NORMAL	NORMAL
Iron	ppm	ASTM D5185m	>500	38	12	39
Chromium	ppm	ASTM D5185m	>20	<1	<1	<1
Nickel	ppm	ASTM D5185m	>10	<1	0	0
Titanium	ppm	ASTM D5185m		<1	0	0
Silver	ppm	ASTM D5185m		0	0	0
Aluminum	ppm	ASTM D5185m	>30	1	<1	1
Lead	ppm	ASTM D5185m	>50	<1	0	0
Copper	ppm	ASTM D5185m	>120	1	0	<1
Tin	ppm	ASTM D5185m	>20	<1	<1	0
Vanadium	ppm	ASTM D5185m		0	0	0
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Silicon	ppm	ASTM D5185m	>50	15	14	15
Potassium	ppm	ASTM D5185m	>20	1	0	0
Water		WC Method	>0.2	NEG	NEG	NEG
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	NEG	NEG	NEG
Sodium	ppm	ASTM D5185m		0	0	0
Boron	ppm	ASTM D5185m		130	143	135
Barium	ppm	ASTM D5185m		0	<1	0
Molybdenum	ppm	ASTM D5185m		1	0	<1
Manganese	ppm	ASTM D5185m		1	<1	2
-						

Magnesium

Phosphorus

Visc @ 40°C

Calcium

Zinc

Sulfur

ppm

ppm

ppm

ppm

ppm

cSt

ASTM D5185m

ASTM D5185m

ASTM D5185m

ASTM D5185m

ASTM D5185m

ASTM D445 55

WEAR NORMAL CONTAMINATION NORMAL FLUID CONDITION NORMAL

Report Id: RECORL [WUSCAR] 06210488 (Generated: 06/17/2024 20:35:07) Rev: 1

Contact/Location: SERVICE MANAGER ? - RECORL

15

4030

1277

1665

4413

43.0

15

4113

1357

1649

4420

42.7

0


4201


1371

1715

4746

42.5







RECYCLE AMERICA Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513 Sample No. Received 12100 YOUNG PINE RD : VCP443032 : 14 Jun 2024 Lab Number : 06210488 Tested ORLANDO, FL : 17 Jun 2024 Diagnosed Unique Number : 11083352 : 17 Jun 2024 - Wes Davis US 32829 Test Package : MOB 1 Contact: SERVICE MANAGER Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Contact/Location: SERVICE MANAGER ? - RECORL Page 2 of 2