WEAR CONTAMINATION **FLUID CONDITION** **NORMAL NORMAL NORMAL**



[RENTAL] **VOLVO EC350 314504**

Rear Right Final Drive

VOLVO PREMIUM GEAR OIL	85W-140 GL-	5 (GAL)				
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Resample at the next service interval to monitor.	Sample Number		Client Info		VCP437326		
	Sample Date		Client Info		16 Apr 2024		
	Machine Age	hrs	Client Info		498		
	Oil Age	hrs	Client Info		0		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		Changed		
	Filter Changed		Client Info		Not Changd		
	Sample Status				NORMAL		
WEAR	Iron	ppm	ASTM D5185m	>500	245		
	Chromium	ppm	ASTM D5185m		5		
All component wear rates are normal.	Nickel	ppm	ASTM D5185m		<1		
	Titanium	ppm	ASTM D5185m		<1		
	Silver	ppm	ASTM D5185m		0		
	Aluminum	ppm	ASTM D5185m	>25	2		
	Lead	ppm	ASTM D5185m		<1		
	Copper	ppm	ASTM D5185m	>50	<1		
	Tin	ppm	ASTM D5185m	>10	0		
	Vanadium	ppm	ASTM D5185m		0		
	White Metal	scalar	*Visual	NONE	MODER		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION	Ciliana		ACTM DE10E-	75	47		
CONTAMINATION	Silicon	ppm	ASTM D5185m		17		
There is no indication of any contamination in the oil.	Potassium Water	ppm	ASTM D5185m WC Method		2 NEG		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>0.2	NEG		
FLUID CONDITION	Sodium	ppm	ASTM D5185m		2		
The condition of the oil is acceptable for the time in service.	Boron	ppm	ASTM D5185m		4		
	Barium	ppm	ASTM D5185m		8		
	Molybdenum	ppm	ASTM D5185m		<1		
	Manganese	ppm	ASTM D5185m		4		
	Magnesium	ppm	ASTM D5185m		3		
	Calcium	ppm	ASTM D5185m		11		
	Phosphorus	ppm	ASTM D5185m		319		
	Zinc	ppm	ASTM D5185m		23		
	Sulfur	ppm	ASTM D5185m		15259		
Pagest Id: V/OLV/00002 [M/I ISCAR] 06210502 (Caparated: 06/22/002/ 04:27:52) Page 1	Visc @ 40°C	cSt	ASTM D445		187		





Certificate L2367

Laboratory Sample No.

Lab Number : 06210503 Unique Number : 11083367

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : VCP437326

Tested Diagnosed Test Package : MOB 1

Received : 14 Jun 2024 : 18 Jun 2024 : 18 Jun 2024 - Sean Felton

8418 PALM RIVER ROAD TAMPA, FL

ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC

US 33619 Contact: KENNY HANEY khaney@flaglerce.com

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

T: (813)630-0077 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (813)630-2233