
**WEAR CONTAMINATION FLUID CONDITION**  **NORMAL NORMAL NORMAL** 





## [ATLAS ORGANIC] VOLVO L70H 623904


**Transmission (Auto)** 

DEXRON III ( GAL)							
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Resample at the next service interval to monitor.	Sample Number		Client Info		ASC0011394		
	Sample Date		Client Info		10 Jun 2024		
	Machine Age	hrs	Client Info		9638		
	Oil Age	hrs	Client Info		1638		
	Filter Age	hrs	Client Info		1638		
	Oil Changed		Client Info		Not Changd		
	Filter Changed		Client Info		Not Changd		
	Sample Status				NORMAL		
WEAR	Iron	ppm	ASTM D5185m	>160	57		
All component wear rates are normal.	Chromium	ppm	ASTM D5185m	>5	<1		
	Nickel	ppm	ASTM D5185m	>5	<1		
	Titanium	ppm	ASTM D5185m		0		
	Silver	ppm	ASTM D5185m	>5	0		
	Aluminum	ppm	ASTM D5185m	>50	3		
	Lead	ppm	ASTM D5185m	>50	0		
	Copper	ppm	ASTM D5185m	>225	6		
	Tin	ppm	ASTM D5185m	>10	<1		
	Vanadium	ppm	ASTM D5185m		0		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION	Silicon	ppm	ASTM D5185m	>20	6		
There is no indication of any contamination in the fluid.	Potassium	ppm	ASTM D5185m	>20	2		
	Water		WC Method	>0.1	NEG		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>0.1	NEG		
FLUID CONDITION	Sodium	ppm	ASTM D5185m		3		
The condition of the fluid is acceptable for the time in service.	Boron	ppm	ASTM D5185m		74		
	Barium	ppm	ASTM D5185m		1		
	Molybdenum	ppm	ASTM D5185m		2		
	Manganese	ppm	ASTM D5185m		4		
	Magnesium	ppm	ASTM D5185m		13		
	Calcium	ppm	ASTM D5185m		105		
	Phosphorus	ppm	ASTM D5185m		227		
	Zinc	ppm	ASTM D5185m		58		
	Sulfur	ppm	ASTM D5185m		1875		
December 1001/1004F7 INITIONAD 00040F00 (Occupant)	Visc @ 40°C	cSt	ASTM D445		28.2	 A DAVELL - A	
Report Id: VOLVO0157 [WUSCAR] 06210599 (Generated: 06/17/2024 16:44:05) Rev: 1			Contact/Lo	cation: T	RENT BRO	ADWELL - \	OLVO0157











Laboratory Sample No.

: ASC0011394 Lab Number : 06210599 Unique Number : 11083463

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 14 Jun 2024 **Tested** : 17 Jun 2024 Diagnosed

: 17 Jun 2024 - Angela Borella

113 - ASCENDUM MACHINERY INC - GARNER 3561 JONES SAUSAGE ROAD

GARNER, NC US 27529

Test Package : CONST Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369.

Contact: TRENT BROADWELL trent.broadwell@ascendummachinery.com T: (919)661-8817

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: (919)661-9038 Contact/Location: TRENT BROADWELL - VOLVO0157