**WEAR** CONTAMINATION **FLUID CONDITION**  **NORMAL NORMAL NORMAL** 

Machine Id

## VOLVO PENTA A1089746

**Starboard Diesel Engine** 

RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
	Sample Number		Client Info		VPA062750		
No corrective action is recommended at this time. Resample at the next service interval to monitor.	Sample Date		Client Info		13 Jun 2024		
	Machine Age	hrs	Client Info		287		
	Oil Age	hrs	Client Info		0		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		N/A		
	Filter Changed		Client Info		N/A		
	Sample Status				NORMAL		
VEAR	Iron	ppm	ASTM D5185m	\80	8		
MEAN	Chromium	ppm	ASTM D5185m		<1		
All component wear rates are normal.	Nickel	ppm	ASTM D5185m		<1		
	Titanium	ppm	ASTM D5185m		<1		
	Silver		ASTM D5185m		0		
	Aluminum	ppm	ASTM D5185m		2		
	Lead	ppm	ASTM D5185m		<1		
	Copper	ppm ppm	ASTM D5185m		3		
	Tin		ASTM D5185m	>9	<1		
	Vanadium	ppm	ASTM D5185m	>5	0		
	White Metal	ppm scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
			Vioudi	NONE			
ONTAMINATION	Silicon	ppm	ASTM D5185m	>25	7		
There is no indication of any contamination in the oil.	Potassium	ppm	ASTM D5185m	>20	1		
	Fuel		WC Method		<1.0		
	Water		WC Method	>0.1	NEG		
	Glycol		WC Method		NEG		
	Soot %	%	*ASTM D7844		0.1		
	Nitration	Abs/cm	*ASTM D7624	>20	4.7		
	Sulfation	Abs/.1mm	*ASTM D7415	>30	18.7		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>0.1	NEG		
LUID CONDITION	Sodium	ppm	ASTM D5185m		2		
The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.	Boron	ppm	ASTM D5185m		60		
	Barium	ppm	ASTM D5185m		0		
	Molybdenum	ppm	ASTM D5185m		48		
	Manganese	ppm	ASTM D5185m		0		
	Magnesium	ppm	ASTM D5185m		649		
	Calcium	ppm	ASTM D5185m		1449		
	Phosphorus	ppm	ASTM D5185m		833		
	Zinc	ppm	ASTM D5185m		1017		
	Sulfur	ppm	ASTM D5185m		3323		
	Oxidation	Abs/.1mm	*ASTM D7414	>25	15.5		
	Base Number (BN)				8.0		
	Visc @ 100°C	cSt	ASTM D445		13.41		





Laboratory Sample No.

: VPA062750 Lab Number : 06210675 Unique Number: 11083539

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received **Tested** 

: 14 Jun 2024 Diagnosed

: 14 Jun 2024 - Doug Bogart

: 14 Jun 2024

Test Package : MOB 1 ( Additional Tests: KV40, TBN )

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Harry's Marine Service LLC

1141 N. Citrus St. Orange, CA US 92887

Contact: TARAH AULD info@harrysmarine.com

T: (714)771-7899 F: