



OIL ANALYSIS REPORT

WEAR	NORMAL
CONTAMINATION	NORMAL
FLUID CONDITION	NORMAL



Area  
**BOWERMAN - ORANGE COUNTY CA**  
Machine Id  
**CATERPILLAR BOW 1**  
Component  
**Biogas Engine**  
Fluid  
**MOBIL PEGASUS 605 (480 GAL)**

**RECOMMENDATION**

Resample at the next service interval to monitor.

Test	UOM	Method	Limit/Abn	Current	History1	History2
Sample Number		Client Info		<b>WC0848227</b>	WC0848214	WC0848264
Sample Date		Client Info		<b>12 Jun 2024</b>	13 May 2024	29 Mar 2024
Machine Age	hrs	Client Info		<b>66004</b>	65203	64320
Oil Age	hrs	Client Info		<b>1249</b>	447	3518
Filter Age	hrs	Client Info		<b>1249</b>	447	3518
Oil Changed		Client Info		<b>Not Changed</b>	Changed	Not Changed
Filter Changed		Client Info		<b>Not Changed</b>	Changed	Not Changed
Sample Status				<b>NORMAL</b>	NORMAL	NORMAL

**WEAR**

All component wear rates are normal.

Iron	ppm	ASTM D5185m	>20	<b>&lt;1</b>	12	2
Chromium	ppm	ASTM D5185m	>5	<b>0</b>	<1	<1
Nickel	ppm	ASTM D5185m	>2	<b>0</b>	<1	<1
Titanium	ppm	ASTM D5185m		<b>0</b>	<1	<1
Silver	ppm	ASTM D5185m	>5	<b>0</b>	0	0
Aluminum	ppm	ASTM D5185m	>15	<b>2</b>	6	2
Lead	ppm	ASTM D5185m	>20	<b>0</b>	<1	<1
Copper	ppm	ASTM D5185m	>15	<b>0</b>	5	<1
Tin	ppm	ASTM D5185m	>5	<b>&lt;1</b>	<1	3
Vanadium	ppm	ASTM D5185m		<b>&lt;1</b>	<1	<1
White Metal	scalar	*Visual	NONE	<b>NONE</b>	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	<b>NONE</b>	NONE	NONE

**CONTAMINATION**













There is no indication of any contamination in the oil.

Silicon	ppm	ASTM D5185m	>150	<b>16</b>	10	20
Potassium	ppm	ASTM D5185m	>20	<b>0</b>	4	1
Fuel		WC Method	>4.0	<b>&lt;1.0</b>	<1.0	<1.0
Water		WC Method	>0.1	<b>NEG</b>	NEG	NEG
Glycol		WC Method		<b>NEG</b>	NEG	NEG
Soot %	%	*ASTM D7844		<b>0</b>	0	0
Nitration	Abs/cm	*ASTM D7624	>20	<b>3.9</b>	3.6	4.5
Sulfation	Abs/.1mm	*ASTM D7415	>30	<b>16.7</b>	16.6	17.5
Silt	scalar	*Visual	NONE	<b>NONE</b>	NONE	NONE
Debris	scalar	*Visual	NONE	<b>NONE</b>	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	<b>NONE</b>	NONE	NONE
Appearance	scalar	*Visual	NORML	<b>NORML</b>	NORML	NORML
Odor	scalar	*Visual	NORML	<b>NORML</b>	NORML	NORML
Emulsified Water	scalar	*Visual	>0.1	<b>NEG</b>	NEG	NEG

**FLUID CONDITION**

The BN result indicates that there is suitable alkalinity remaining in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

Sodium	ppm	ASTM D5185m		<b>1</b>	16	<1
Boron	ppm	ASTM D5185m		<b>95</b>	15	69
Barium	ppm	ASTM D5185m		<b>0</b>	0	0
Molybdenum	ppm	ASTM D5185m		<b>&lt;1</b>	1	2
Manganese	ppm	ASTM D5185m		<b>0</b>	1	<1
Magnesium	ppm	ASTM D5185m		<b>4</b>	36	11
Calcium	ppm	ASTM D5185m		<b>1676</b>	1354	1575
Phosphorus	ppm	ASTM D5185m		<b>420</b>	485	401
Zinc	ppm	ASTM D5185m		<b>553</b>	573	556
Sulfur	ppm	ASTM D5185m		<b>3985</b>	1813	3843
Oxidation	Abs/.1mm	*ASTM D7414	>25	<b>10.7</b>	9.9	11.6
Acid Number (AN)	mg KOH/g	ASTM D8045		<b>0.69</b>	0.53	0.947
Base Number (BN)	mg KOH/g	ASTM D2896	7.1	<b>4.53</b>	5.16	4.14
Visc @ 100°C	cSt	ASTM D445	13.3	<b>14.5</b>	14.3	14.5



Certificate L2367

**Laboratory** : WearCheck USA - 501 Madison Ave., Cary, NC 27513  
**Sample No.** : WC0848227  
**Lab Number** : 06210878  
**Unique Number** : 11083742  
**Test Package** : MOB 2

**Received** : 14 Jun 2024  
**Tested** : 18 Jun 2024  
**Diagnosed** : 18 Jun 2024 - Sean Felton

**MONTAUK ENERGY CAPITAL LLC (TEXAS) LP**  
 1412 N SAM HOUSTON PKWY E, SUITE 100  
 HOUSTON, TX  
 US 77032

Contact: DAMON MCCLENAN  
 dmcclenan@montaukenergy.com

T: (713)781-1126  
 F: (713)781-1127

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)