WEAR CONTAMINATION FLUID CONDITION

NORMAL NORMAL

[SPM728584 FRITZ]

VOLVO 992G ADZ00488

Rear Left Final Drive

Resample at the next service interval to monitor.	Test	UOM	Method	Limit/Abn	Current	History1	History2
	Sample Number	OOW	Client Info	LIIII0710II	VCP443778		
	Sample Date		Client Info		07 Jun 2024		
	Machine Age	hrs	Client Info		0		
	Oil Age	hrs	Client Info		0		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		Changed		
	Filter Changed		Client Info		Changed		
	Sample Status				NORMAL		
VEAD							
WEAR	Iron	ppm	ASTM D5185m		8		
All component wear rates are normal.	Chromium	ppm	ASTM D5185m		0		
	Nickel	ppm	ASTM D5185m	>10	0		
	Titanium Silver	ppm	ASTM D5185m ASTM D5185m		<1		
	Aluminum	ppm	ASTM D5185m	×25	0 <1		
	Lead	ppm	ASTM D5185m		0		
	Copper	ppm	ASTM D5185m		1		
	Tin	ppm	ASTM D5185m		0		
	Vanadium	ppm	ASTM D5185m	>10	<1		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION	Silicon	ppm	ASTM D5185m	>75	6		
There is no indication of any contamination in the oil.	Potassium	ppm	ASTM D5185m	>20	0		
	Water		WC Method	>0.2	NEG		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>0.2	NEG		
LUID CONDITION	Sodium	ppm	ASTM D5185m		3		
The condition of the oil is acceptable for the time in service.	Boron	ppm	ASTM D5185m	37	0		
The condition of the on is acceptable for the time in service.	Barium	ppm	ASTM D5185m		0		
	Molybdenum	ppm	ASTM D5185m	5	0		
	Manganese	ppm	ASTM D5185m		<1		
	Magnesium	ppm	ASTM D5185m	40	11		
	Calcium	ppm	ASTM D5185m	2650	3169		
	Phosphorus	ppm	ASTM D5185m	1050	1207		
	Zinc	ppm	ASTM D5185m	1075	1218		
	Sulfur	ppm	ASTM D5185m	5750	11306		







Certificate L2367

Report Id: VOLVO8885 [WUSCAR] 06215059 (Generated: 06/21/2024 13:07:47) Rev: 1

Laboratory Sample No.

Lab Number : 06215059 Unique Number : 11087923

: VCP443778

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 19 Jun 2024 **Tested**

: 20 Jun 2024 Diagnosed

: 21 Jun 2024 - Sean Felton

ALTA EQUIPMENT CO - ORLAND PARK 5000 INDUSTRIAL HWY GARY, IN

US 46406 Contact: DAVE ENG

DAVE.ENG@ALTG.COM T: (312)350-2560

Test Package : MOB 1 To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Contact/Location: DAVE ENG - VOLVO8885