WEAR CONTAMINATION **FLUID CONDITION** **NORMAL NORMAL NORMAL**

Machine Id

NOT GIVEN IL06217773 Component Diesel Engine

{not provided} (--- GAL)

| RECOMMENDATION | Test | UOM | Method | Limit/Abn | Current | History1 | History2 |
|---|------------------|----------|-------------------|-----------|-------------|----------|----------|
| Resample at the next service interval to monitor. | Sample Number | | Client Info | | IL06217773 | | |
| | Sample Date | | Client Info | | 23 Jun 2024 | | |
| | Machine Age | mls | Client Info | | 0 | | |
| | Oil Age | mls | Client Info | | 0 | | |
| | Filter Age | mls | Client Info | | 0 | | |
| | Oil Changed | | Client Info | | N/A | | |
| | Filter Changed | | Client Info | | N/A | | |
| | Sample Status | | | | NORMAL | | |
| VEAR | Iron | ppm | ASTM D5185m | >100 | 13 | | |
| All component wear rates are normal. | Chromium | ppm | ASTM D5185m | >20 | <1 | | |
| | Nickel | ppm | ASTM D5185m | | 0 | | |
| | Titanium | ppm | ASTM D5185m | | 0 | | |
| | Silver | ppm | ASTM D5185m | >3 | 0 | | |
| | Aluminum | ppm | ASTM D5185m | | 2 | | |
| | Lead | ppm | ASTM D5185m | | - <1 | | |
| | Copper | ppm | ASTM D5185m | | <1 | | |
| | Tin | ppm | ASTM D5185m | | 0 | | |
| | Vanadium | ppm | ASTM D5185m | | <1 | | |
| | White Metal | scalar | *Visual | NONE | NONE | | |
| | Yellow Metal | scalar | *Visual | NONE | NONE | | |
| | | | | | | | |
| CONTAMINATION | Silicon | ppm | ASTM D5185m | >25 | 6 | | |
| There is no indication of any contamination in the oil. | Potassium | ppm | ASTM D5185m | >20 | 1 | | |
| | Fuel | % | ASTM D3524 | >5 | <1.0 | | |
| | Water | | WC Method | >0.2 | NEG | | |
| | Glycol | | WC Method | | NEG | | |
| | Soot % | % | *ASTM D7844 | >3 | 0.3 | | |
| | Nitration | Abs/cm | *ASTM D7624 | >20 | 9.1 | | |
| | Sulfation | Abs/.1mm | *ASTM D7415 | >30 | 21.7 | | |
| | Silt | scalar | *Visual | NONE | NONE | | |
| | Debris | scalar | *Visual | NONE | NONE | | |
| | Sand/Dirt | scalar | *Visual | NONE | NONE | | |
| | Appearance | scalar | *Visual | NORML | NORML | | |
| | Odor | scalar | *Visual | NORML | NORML | | |
| | Emulsified Water | scalar | *Visual | >0.2 | NEG | | |
| LUID CONDITION | Sodium | ppm | ASTM D5185m | | 2 | | |
| The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is acceptable for the time in service. | Boron | ppm | ASTM D5185m | | 44 | | |
| | Barium | ppm | ASTM D5185m | | 0 | | |
| | Molybdenum | ppm | ASTM D5185m | | 60 | | |
| | Manganese | ppm | ASTM D5185m | | <1 | | |
| | Magnesium | ppm | ASTM D5185m | | 482 | | |
| | Calcium | ppm | ASTM D5185m | | 1716 | | |
| | Phosphorus | ppm | ASTM D5185m | | 773 | | |
| | Zinc | ppm | ASTM D5185m | | 904 | | |
| | Sulfur | ppm | ASTM D5185m | | 2656 | | |
| | Oxidation | Abs/.1mm | *ASTM D7414 | >25 | 20.7 | | |
| | Base Number (BN) | | ASTM D2896 | /20 | 8.9 | | |
| | | my nony | , (O I IVI D 2000 | | 0.0 | | |







Laboratory Sample No.

Lab Number : 06217773 Unique Number : 11095970

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : IL06217773

Received **Tested**

: 25 Jun 2024 Diagnosed

: 25 Jun 2024 - Don Baldridge Test Package: FLEET (Additional Tests: FuelDilution, PercentFuel)

: 24 Jun 2024

4571 NORTH BUFORD HWY NORCROSS, GA US 30071-2808

Contact: RICK MARKS

IDEALEASE-NORCROSS

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: (770)300-0614

Contact/Location: RICK MARKS - IDENORGA