WEAR CONTAMINATION FLUID CONDITION

ABNORMAL NORMAL NORMAL




[HERC] Wolvo ECR145 315945 Component Rear Left Final Drive

GEAR OIL SAE 85W140 (GA	L)						
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
The oil change at the time of sampling has been noted. Resample at the next service interval to monitor.	Sample Number		Client Info		VCP445600		
	Sample Date		Client Info		17 Jun 2024		
	Machine Age	hrs	Client Info		839		
	Oil Age	hrs	Client Info		0		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		Changed		
	Filter Changed		Client Info		Not Changd		
	Sample Status				ABNORMAL		
WEAR	Iron	ppm	ASTM D5185m	>500	 <u>▲</u> 532		
Bearing and/or gear wear is indicated.	Chromium	ppm	ASTM D5185m		<u>▲</u> 13		
	Nickel	ppm	ASTM D5185m		1		
	Titanium	ppm	ASTM D5185m	>10	<1		
	Silver	ppm	ASTM D5185m		<1		
	Aluminum	ppm	ASTM D5185m	>25	3		
	Lead	ppm	ASTM D5185m		1		
	Copper	ppm	ASTM D5185m	>50	2		
	Tin	ppm	ASTM D5185m	>10	▲ 37		
	Vanadium	ppm	ASTM D5185m		<1		
	White Metal	scalar	*Visual	NONE	MODER		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTABBINATION							
CONTAMINATION There is no indication of any contamination in the oil.	Silicon	ppm	ASTM D5185m		16		
	Potassium	ppm	ASTM D5185m		2		
	Water		WC Method		NEG		
	Silt	scalar	*Visual	NONE	NONE NONE		
	Debris Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water			>0.2	NEG		
			····				
FLUID CONDITION	Sodium	ppm	ASTM D5185m		7		
The condition of the oil is acceptable for the time in service.	Boron	ppm	ASTM D5185m	400	4		
	Barium	ppm	ASTM D5185m		3		
	Molybdenum	ppm	ASTM D5185m	12	1		
	Manganese	ppm	ASTM D5185m		9		
	Magnesium	ppm	ASTM D5185m		2		
	Calcium	ppm	ASTM D5185m		103		
	Phosphorus	ppm	ASTM D5185m		271		
	Zinc	ppm		125	69		
	Sulfur	ppm	ASTM D5185m	22500	13090		

Visc @ 40°C

137

ASTM D445 368





Certificate L2367

Laboratory Sample No.

Lab Number : 06218595

Test Package : MOB 1

: VCP445600 Unique Number : 11096792

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received **Tested**

: 24 Jun 2024 : 25 Jun 2024 Diagnosed

: 26 Jun 2024 - Jonathan Hester

ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC 8418 PALM RIVER ROAD

TAMPA, FL US 33619

Contact: KENNY HANEY khaney@flaglerce.com

T: (813)630-0077 F: (813)630-2233

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)