

Machine Id

mnonen

TO .

## JOHN DEERE 544K 1DW544KZVJF690193

Gearbox

{not provided} (--- GAL)

RECOMMENDATION

We advise that you check all areas where dirt can enter the system. We recommend that you drain the oil from the component if this has not already been done. We advise that you inspect for the source(s) of wear. We recommend an early resample to monitor this condition.

## WEAR

Gear wear is indicated.

## CONTAMINATION


Elemental levels of silicon (Si) and aluminum (Al) indicate aluminasilicate (coarse dirt) ingress.

## FLUID CONDITION

The oil is no longer serviceable due to the presence of contaminants.

				$\frown$		
Test	UOM	Method	Limit/Abn	Current	History1	History2
Sample Number		Client Info		JR0223098		
Sample Date		Client Info		25 Jun 2024		
Machine Age	hrs	Client Info		3957		
Oil Age	hrs	Client Info		0		
Filter Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Filter Changed		Client Info		N/A		
Sample Status				SEVERE		
PQ		ASTM D8184		<b>1</b> 98		
Iron	ppm	ASTM D5185m	>200	<b>4</b> 09		
Chromium	ppm	ASTM D5185m	>10	1		
Nickel	ppm	ASTM D5185m	>10	2		
Titanium	ppm	ASTM D5185m		8		
Silver	ppm	ASTM D5185m		<1		
Aluminum	ppm	ASTM D5185m	>25	<b>7</b> 4		
Lead	ppm	ASTM D5185m	>50	4		
Copper	ppm	ASTM D5185m	>200	10		
Tin	ppm	ASTM D5185m	>10	<1		
Vanadium	ppm	ASTM D5185m		<1		
White Metal	scalar	*Visual	NONE	NONE		
Yellow Metal	scalar	*Visual	NONE	NONE		
Silicon	ppm	ASTM D5185m	>50	<b>4</b> 347		
Potassium	ppm	ASTM D5185m	>20	32		
Water		WC Method	>0.2	NEG		
Silt	scalar	*Visual	NONE	NONE		
Debris	scalar	*Visual	NONE	NONE		
Sand/Dirt	scalar	*Visual	NONE	NONE		
Appearance	scalar	*Visual	NORML	NORML		
Odor	scalar	*Visual	NORML	NORML		
Emulsified Water	scalar	*Visual	>0.2	NEG		
Sodium	ppm	ASTM D5185m		63		
Boron	ppm	ASTM D5185m		73		
Barium	ppm	ASTM D5185m		14		
Molybdenum	ppm	ASTM D5185m		9		
Manganese	ppm	ASTM D5185m		6		
Magnesium	ppm	ASTM D5185m		109		
Calcium	ppm	ASTM D5185m		2724		
Phosphorus	ppm	ASTM D5185m		896		
Zinc	ppm	ASTM D5185m		1099		
0.11		ACTM DE105m		2014		
Sulfur	ppm	ASTM D5185m		3914		

Contact/Location: NICK GALLAHER - JAMGRE



Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513 **JRE - GREENSBORO** Sample No. : JR0223098 Received : 25 Jun 2024 411 SOUTH REGIONAL ROAD £ Lab Number : 06219973 Tested GREENSBORO, NC : 26 Jun 2024 Unique Number : 11098170 : 26 Jun 2024 - Sean Felton US 27409 Diagnosed Test Package : CONST (Additional Tests: PQ) Contact: NICK GALLAHER Certificate L2367 NGALLAHER@JRENET.COM To discuss this sample report, contact Customer Service at 1-800-237-1369. \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. T: (336)668-2762 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (336)665-9556

Contact/Location: NICK GALLAHER - JAMGRE Page 2 of 2