

WEAR CONTAMINATION FLUID CONDITION

NORMAL NORMAL NORMAL

Area

[1051]




## **VOLVO L70H 624405**


Diesel Exhaust Fluid (DEF)

DEF (Diesel Exaust Fluid) (--- GAL)

	· <i>'</i>						
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Fluid meets ISO 22241-2 requirements and is suitable for use.	Sample Number		Client Info		VCP437473		
	Sample Date		Client Info		19 Jun 2024		
	Machine Age	hrs	Client Info		1764		
	Oil Age	hrs	Client Info		0		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		Not Changd		
	Filter Changed		Client Info		N/A		
	Sample Status				NORMAL		
WEAR	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION	Hydrocarbon	scalar	*In-House		NONE		
Appearance is acceptable. There is no indication of any contamination	Hydrocarbon Silt	scalar scalar	*In-House  *Visual	NONE	NONE NONE		
	·			NONE NONE			
Appearance is acceptable. There is no indication of any contamination	Silt	scalar	*Visual		NONE		
Appearance is acceptable. There is no indication of any contamination	Silt Debris	scalar scalar	*Visual	NONE	NONE NONE		
Appearance is acceptable. There is no indication of any contamination	Silt Debris Sand/Dirt	scalar scalar scalar	*Visual  *Visual	NONE	NONE NONE		
Appearance is acceptable. There is no indication of any contamination	Silt Debris Sand/Dirt Appearance	scalar scalar scalar scalar	*Visual  *Visual  *Visual  *Visual	NONE NORML	NONE NONE NONE NORML		   
Appearance is acceptable. There is no indication of any contamination in the diesel exhaust fluid (def).	Silt Debris Sand/Dirt Appearance Odor Emulsified Water	scalar scalar scalar scalar scalar scalar	*Visual  *Visual  *Visual  *Visual  *Visual  *Visual	NONE NONE NORML NORML	NONE NONE NORML NORML 0.2%	  	
Appearance is acceptable. There is no indication of any contamination in the diesel exhaust fluid (def).  FLUID CONDITION	Silt Debris Sand/Dirt Appearance Odor Emulsified Water Urea Content	scalar scalar scalar scalar scalar scalar	*Visual  *Visual  *Visual  *Visual  *Visual  *Visual  ISO 22241	NONE NORML NORML <31.8	NONE NONE NORML NORML 0.2%	   	
Appearance is acceptable. There is no indication of any contamination in the diesel exhaust fluid (def).	Silt Debris Sand/Dirt Appearance Odor Emulsified Water Urea Content Density @ 20°C	scalar scalar scalar scalar scalar scalar	*Visual  *Visual  *Visual  *Visual  *Visual  *Visual  ISO 22241	NONE NORML NORML <31.8 >1.0930	NONE NONE NORML NORML 0.2% 32.4 1.0887	   	
Appearance is acceptable. There is no indication of any contamination in the diesel exhaust fluid (def).  FLUID CONDITION	Silt Debris Sand/Dirt Appearance Odor Emulsified Water Urea Content	scalar scalar scalar scalar scalar scalar	*Visual  *Visual  *Visual  *Visual  *Visual  *Visual  ISO 22241	NONE NORML NORML <31.8	NONE NONE NORML NORML 0.2%	   	



200







Laboratory Sample No.

Lab Number : 06220619 Unique Number : 11098816

: VCP437473

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 25 Jun 2024 **Tested** : 03 Jul 2024

Diagnosed : 03 Jul 2024 - Doug Bogart Test Package : DEF 1 (Additional Tests: ICP, KF, SCREEN)

12345 MAPLEVIEW STREET LAKESIDE, CA

> Contact: Mark Stewart mark.stewart@vcesvolvo.com

VCES- VOLVO CONSTRUCTION EQUIPMENT

T: X: F: X:

To discuss this sample report, contact Customer Service at 1-800-237-1369. \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

US 92040