

WEAR CONTAMINATION FLUID CONDITION

NORMAL NORMAL


UTILITIES Machine Id


FUEL STATION 3 UNITED RENTALS

Diesel Exhaust Fluid (DEF)

DEF (Diesel Exaust Fluid) (275 GAL)

DEI (DICCCI EXCUST I I III I) (ETO GAE)					.,		
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Fluid meets ISO 22241-2 requirements and is suitable for use.	Sample Number		Client Info		RP0044216	RP0044088	RP0042517
	Sample Date		Client Info		26 Jun 2024	06 Jun 2024	08 May 2024
	Machine Age	mls	Client Info		0	0	0
	Oil Age	mls	Client Info		0	0	0
	Filter Age	mls	Client Info		0	0	0
	Oil Changed		Client Info		N/A	N/A	N/A
	Filter Changed		Client Info		N/A	N/A	N/A
	Sample Status				NORMAL	NORMAL	NORMAL
WEAR	White Metal	scalar	*Visual	NONE		NONE	
	Yellow Metal	scalar	*Visual	NONE		NONE	
CONTAMINATION	Hydrocarbon	scalar	*In-House		NONE	NONE	NONE
Appearance is acceptable. There is no indication of any contamination in the diesel exhaust fluid (def).	Silt	scalar	*Visual	NONE		NONE	
	Debris	scalar	*Visual	NONE		NONE	
	Sand/Dirt	scalar	*Visual	NONE		NONE	
	Appearance	scalar	*Visual	NORML		NORML	
	Odor	scalar	*Visual	NORML		NORML	
	Emulsified Water	scalar	*Visual			NEG	
FLUID CONDITION	Urea Content	%	ISO 22241	<31.8	32.7	32.6	32.7
Urea content is normal.	Density @ 20°C	g/cm3	ISO 22241	>1.0930	1.0893	1.0884	1.0895
	Refracting Index		ISO 22241	<1.3814	1.3828	1.3826	1.3827
	Appearance	scalar	*Visual		Clear & Bright	Clear & Bright	Clear & Bright







: 27 Jun 2024



Certificate L2367

Laboratory Sample No.

Lab Number : 06222813 Unique Number : 11101010

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : RP0044216 Received **Tested**

: 05 Jul 2024 Diagnosed : 05 Jul 2024 - Doug Bogart

Test Package : DEF 1 (Additional Tests: ICP, KF, KV40, SCREEN, TAN Man) To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

OUTOKUMPU STAINLESS USA

HWY 43 N CALVERT, AL US 36513

Contact: MARIO JOHNSON Mario.johnson@outokumpu.com

T: (251)321-4105 F: x:

Submitted By: DALE ROBINSON