CORROSION
CONTAMINANTS
COOLANT CONDITION

NORMAL NORMAL NORMAL


Machine Id

JOHN DEERE 544 P 1DW544PACPLZ16938

Component Coolant

{not provided} (--- GAL)

RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
The fluid is suitable for further service.	Sample Number		Client Info		JR0223377		
	Sample Date		Client Info		30 Jun 2024		
	Machine Age	hrs	Client Info		1971		
	Oil Age	hrs	Client Info		0		
	Oil Changed		Client Info		N/A		
	Sample Status				NORMAL		
CORROSION	Total Dissolved Solids				312.5		
	Coolant Appearance		*Visual	Clear	normal		
CONTAMINANTS	Boiling Point	°C	WC Method		225		
There is no indication of any contamination in the coolant.	Specific Gravity		*ASTM D1298		1.065		
	рН	Scale 0-14	ASTM D1287		8.37		
	Nitrites	ppm	AP-053:2009		NT		
	Reserve Alkalinity	Scale 0-20	*ASTM D1121				
	Percentage Glycol	%	ASTM D3321		48.6		
	Freezing Point	°F	ASTM D3321		-31		
	Carboxylate				n/a		
	Coolant Color		*Visual		Yllow		





Certificate L2367

Laboratory Sample No.

: WearCheck USA - 501 Madison Ave., Cary, NC 27513

: JR0223377 Lab Number : 06224968 Unique Number : 11103165

Received **Tested**

Diagnosed Test Package : COOL- (Additional Tests: GlycolType, PQ)

: 03 Jul 2024

: 01 Jul 2024

: 03 Jul 2024 - Jonathan Hester

US 27409 Contact: NICK GALLAHER NGALLAHER@JRENET.COM

411 SOUTH REGIONAL ROAD

JRE - GREENSBORO

GREENSBORO, NC

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation. T: (336)668-2762 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (336)665-9556