WEAR CONTAMINATION FLUID CONDITION

NORMAL NORMAL


[W51111]

JOHN DEERE 750L 1T0750LXEPF444889

Right Inner Final Drive

JOHN DEERE HY-GARD HYD/TRANS (4 GAL)

History2
s i





Laboratory

Sample No.

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : JR0222224 Lab Number : 06228898 Unique Number : 11112391

Received **Tested**

: 05 Jul 2024 : 08 Jul 2024 Diagnosed : 08 Jul 2024 - Don Baldridge

JRE - STEPHENSON 245 YARDMASTER COURT STEPHENSON, VA US 22656-1761 Contact: PHIL DAUGHERTY

Test Package : CONST (Additional Tests: PQ) Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369.

pdaugherty@jamesriverequipment.com T: x:

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: (540)693-2588