WEAR CONTAMINATION FLUID CONDITION


NORMAL NORMAL


Machine Id **VOLVO A45G 342398**


Brake Cooling System


VOLVO SUPER WET BRAKE TRANSAXLE OIL WB102 (--- GAL)

VOLVO SUPER WEI BRAKE	IIIAIIOAALL	OIL !	VD 102 (`		
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Resample at the next service interval to monitor.	Sample Number		Client Info		ML0002624	ML0001505	
	Sample Date		Client Info		28 Jun 2024	15 Apr 2024	
	Machine Age	hrs	Client Info		7961	7441	
	Oil Age	hrs	Client Info		520	4000	
	Filter Age	hrs	Client Info		0	0	
	Oil Changed		Client Info		N/A	Changed	
	Filter Changed		Client Info		N/A	Changed	
	Sample Status				NORMAL	NORMAL	
WEAR	Iron	nnm	ASTM D5185m	<u>~50</u>	6	4	
	Chromium	ppm	ASTM D5185m		<1	0	
All component wear rates are normal.	Nickel	ppm	ASTM D5185m		<1	0	
	Titanium	ppm	ASTM D5185m	>10	1	0	
	Silver	ppm	ASTM D5185m		- <1	0	
	Aluminum	ppm	ASTM D5185m	\3 0	2	<1	
	Lead	ppm	ASTM D5185m		<1	0	
	Copper	ppm	ASTM D5185m		22	20	
	Tin	ppm	ASTM D5185m		<1	0	
	Vanadium	ppm	ASTM D5185m	720	<1	0	
	White Metal	scalar	*Visual	NONE	NONE	NONE	
	Yellow Metal	scalar	*Visual	NONE	NONE	NONE	
CONTAMINATION	Silicon	ppm	ASTM D5185m	>50	10	12	
There is no indication of any contamination in the oil.	Potassium	ppm	ASTM D5185m		2	0	
	Water		WC Method	>0.2	NEG	NEG	
	Silt	scalar	*Visual	NONE	NONE	NONE	
	Debris	scalar	*Visual	NONE	NONE	NONE	
	Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	
	Appearance	scalar	*Visual	NORML	NORML	NORML	
	Odor	scalar	*Visual	NORML	NORML	NORML	
	Emulsified Water	scalar	*Visual	>0.2	NEG	NEG	
FLUID CONDITION	Sodium	ppm	ASTM D5185m		<1	1	
The condition of the oil is acceptable for the time in service.	Boron	ppm	ASTM D5185m		99	93	
	Barium	ppm	ASTM D5185m		0	0	
	Molybdenum	ppm	ASTM D5185m		<1	0	
	Manganese	ppm	ASTM D5185m		<1	<1	
	Magnesium	ppm	ASTM D5185m		7	<1	
	Calcium	ppm	ASTM D5185m		3752	3627	
	Phosphorus	ppm	ASTM D5185m		1314	1245	
	Zinc	ppm	ASTM D5185m		1665	1498	
	Sulfur	ppm	ASTM D5185m		4437	4686	
	Visc @ 40°C	cSt	ASTM D445	55	42.5	47.4	











Laboratory Sample No.

Lab Number : 06229353 Unique Number : 11112846

: ML0002624

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 05 Jul 2024 **Tested** : 09 Jul 2024 Diagnosed

: 09 Jul 2024 - Don Baldridge

MCCLUNG-LOGAN EQUIPMENT CO - BALTIMORE 4601 WASHINGTON BOULEVARD BALTIMORE, MD

US 21227 Contact: MARK CIULLA

T: (410)242-6500

F: (410)242-7835

mciulla@mcclung-logan.com

Test Package : CONST Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)