
WEAR CONTAMINATION **FLUID CONDITION**


NORMAL NORMAL NORMAL





Machine Id 420096 1 Differential

{not provided} (GAL)							
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Resample at the next service interval to monitor. (Customer Sample Comment: 1st Axle / Pusher)	Sample Number		Client Info		GFL0123510		
	Sample Date		Client Info		02 Jul 2024		
	Machine Age	hrs	Client Info		142429		
	Oil Age	hrs	Client Info		142429		
	Filter Age	hrs	Client Info		142429		
	Oil Changed		Client Info		N/A		
	Filter Changed		Client Info		N/A		
	Sample Status				NORMAL		
WEAR	Iron	ppm	ASTM D5185m	>1200	96		
All component wear rates are normal.	Chromium	ppm	ASTM D5185m		<1		
	Nickel	ppm	ASTM D5185m		3		
	Titanium	ppm	ASTM D5185m		0		
	Silver	ppm	ASTM D5185m		0		
	Aluminum	ppm	ASTM D5185m	>30	5		
	Lead	ppm	ASTM D5185m		<1		
	Copper	ppm	ASTM D5185m	>50	2		
	Tin	ppm	ASTM D5185m	>5	0		
	Vanadium	ppm	ASTM D5185m		0		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION							
CONTAMINATION	Silicon	ppm	ASTM D5185m		49		
There is no indication of any contamination in the oil.	Potassium	ppm	ASTM D5185m		2		
	Water		WC Method	>.2	NEG		
	Silt	scalar	*Visual	NONE	NONE		
	Debris Cond/Dist	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE NORML	NONE NORML		
	Appearance Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water		*Visual	>.2	NEG		
FLUID CONDITION	Sodium	ppm	ASTM D5185m		2		
The condition of the oil is acceptable for the time in service.	Boron	ppm	ASTM D5185m		23		
	Barium	ppm	ASTM D5185m		0		
	Molybdenum	ppm	ASTM D5185m		0		
	Manganese	ppm	ASTM D5185m		2		
	Magnesium	ppm	ASTM D5185m		1		
	Calcium	ppm	ASTM D5185m		23		
	Phosphorus	ppm	ASTM D5185m		549		
	Zinc	ppm	ASTM D5185m		20		
	Sulfur	ppm	ASTM D5185m		19084		
Papart Id: CEI 002 IA/I ICCAPI 06220691 (Caparated: 07/10/2024 11:22:12) Pays 1	Visc @ 40°C	cSt	ASTM D445	C Is	43.0		











Certificate L2367

Laboratory Sample No.

: GFL0123510 Lab Number : 06230581 Unique Number : 11114074 Test Package : FLEET

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 08 Jul 2024 **Tested** : 10 Jul 2024

Diagnosed

: 10 Jul 2024 - Sean Felton

GFL Environmental - 983 - Sugar Land Hauling 16011 West Belfort Street

Sugar Land, TX US 77498

Contact: TECHNICIAN ACCOUNT wcgfldemo@gmail.com

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. T: Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: