



WEAR	<b>NORMAL</b>
CONTAMINATION	<b>NORMAL</b>
FLUID CONDITION	<b>NORMAL</b>

Machine Id  
**SDA**  
Component  
**Steering**  
Fluid  
**CHEVRON HYDRAULIC AW ISO 68 (150 GAL)**

**RECOMMENDATION**

Resample at the next service interval to monitor.

Test	UOM	Method	Limit/Abn	Current	History1	History2
Sample Number		Client Info		<b>MW0070365</b>	MW0065350	MW0055072
Sample Date		Client Info		<b>28 Jun 2024</b>	22 Mar 2024	19 Sep 2023
Machine Age	hrs	Client Info		<b>0</b>	0	37198
Oil Age	hrs	Client Info		<b>43301</b>	41218	37198
Filter Age	hrs	Client Info		<b>0</b>	0	0
Oil Changed		Client Info		<b>Not Changd</b>	Not Changd	Not Changd
Filter Changed		Client Info		<b>Not Changd</b>	N/A	N/A
Sample Status				<b>NORMAL</b>	ABNORMAL	ABNORMAL

**WEAR**

All component wear rates are normal.

Iron	ppm	ASTM D5185m	>50	<b>0</b>	3	<1
Chromium	ppm	ASTM D5185m	>15	<b>0</b>	<1	0
Nickel	ppm	ASTM D5185m	>5	<b>0</b>	<1	0
Titanium	ppm	ASTM D5185m		<b>0</b>	<1	0
Silver	ppm	ASTM D5185m		<b>0</b>	0	0
Aluminum	ppm	ASTM D5185m	>5	<b>0</b>	2	0
Lead	ppm	ASTM D5185m	>10	<b>0</b>	2	<1
Copper	ppm	ASTM D5185m	>50	<b>0</b>	19	20
Tin	ppm	ASTM D5185m	>5	<b>0</b>	2	<1
Vanadium	ppm	ASTM D5185m		<b>0</b>	<1	0
White Metal	scalar	*Visual	NONE	<b>NONE</b>	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	<b>NONE</b>	NONE	NONE

**CONTAMINATION**










The amount and size of particulates present in the system are acceptable. There is no indication of any contamination in the oil.

Silicon	ppm	ASTM D5185m	>15	<b>0</b>	1	<1
Potassium	ppm	ASTM D5185m	>20	<b>0</b>	<1	0
Water		WC Method	>0.2	<b>NEG</b>	NEG	NEG
Particles >4µm		ASTM D7647		<b>835</b>	85895	32040
Particles >6µm		ASTM D7647	>1300	<b>113</b>	▲ 16838	▲ 3013
Particles >14µm		ASTM D7647	>160	<b>5</b>	▲ 755	37
Particles >21µm		ASTM D7647	>40	<b>1</b>	▲ 169	6
Particles >38µm		ASTM D7647	>10	<b>0</b>	6	0
Particles >71µm		ASTM D7647	>3	<b>0</b>	2	0
Oil Cleanliness		ISO 4406 (c)	>-/17/14	<b>17/14/10</b>	▲ 24/21/17	▲ 22/19/12
Silt	scalar	*Visual	NONE	<b>NONE</b>	NONE	NONE
Debris	scalar	*Visual	NONE	<b>NONE</b>	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	<b>NONE</b>	NONE	NONE
Appearance	scalar	*Visual	NORML	<b>NORML</b>	NORML	NORML
Odor	scalar	*Visual	NORML	<b>NORML</b>	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	<b>NEG</b>	NEG	NEG

**FLUID CONDITION**

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

Sodium	ppm	ASTM D5185m		<b>0</b>	0	2
Boron	ppm	ASTM D5185m		<b>0</b>	0	0
Barium	ppm	ASTM D5185m		<b>0</b>	0	0
Molybdenum	ppm	ASTM D5185m		<b>0</b>	2	0
Manganese	ppm	ASTM D5185m		<b>0</b>	<1	<1
Magnesium	ppm	ASTM D5185m		<b>1</b>	20	0
Calcium	ppm	ASTM D5185m		<b>38</b>	66	43
Phosphorus	ppm	ASTM D5185m		<b>373</b>	330	285
Zinc	ppm	ASTM D5185m		<b>442</b>	382	328
Sulfur	ppm	ASTM D5185m		<b>950</b>	763	686
Acid Number (AN)	mg KOH/g	ASTM D8045		<b>0.42</b>	0.39	0.38
Visc @ 40°C	cSt	ASTM D445	64.6	<b>68.3</b>	68.2	67.6



Certificate L2367

**Laboratory** : WearCheck USA - 501 Madison Ave., Cary, NC 27513  
**Sample No.** : MW0070365  
**Lab Number** : 06233817  
**Unique Number** : 11122651  
**Test Package** : MAR 2 ( Additional Tests: PrtCount )

**AMERICAN RIVER TRANSPORTATION CO.**  
 P.O. BOX 2889  
 ST. LOUIS, MO  
 US 63111  
 Contact: BRIAN GRIEWING  
 brian.griewing@adm.com

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T:  
 F: (314)481-5278