



# OIL ANALYSIS REPORT

WEAR	NORMAL
CONTAMINATION	NORMAL
FLUID CONDITION	NORMAL

Machine Id  
**BUS 743**  
 Component  
**Diesel Engine**  
 Fluid  
**CHEVRON DELO 400 LE 15W40 (--- GAL)**

## RECOMMENDATION

Resample at the next service interval to monitor. Please specify the component make and model with your next sample.

Test	UOM	Method	Limit/Abn	Current	History1	History2
Sample Number		Client Info		<b>DC0037505</b>	DC0031896	DC0028473
Sample Date		Client Info		<b>18 Jun 2024</b>	07 Feb 2024	18 Sep 2023
Machine Age	mls	Client Info		<b>130692</b>	114887	97135
Oil Age	mls	Client Info		<b>0</b>	0	0
Filter Age	mls	Client Info		<b>0</b>	0	0
Oil Changed		Client Info		<b>Changed</b>	Changed	Changed
Filter Changed		Client Info		<b>Changed</b>	Changed	Changed
Sample Status				<b>NORMAL</b>	NORMAL	NORMAL

## WEAR

All component wear rates are normal.

Iron	ppm	ASTM D5185m	>100	<b>15</b>	20	20
Chromium	ppm	ASTM D5185m	>20	<b>1</b>	1	1
Nickel	ppm	ASTM D5185m	>4	<b>0</b>	<1	0
Titanium	ppm	ASTM D5185m		<b>&lt;1</b>	<1	0
Silver	ppm	ASTM D5185m	>3	<b>0</b>	0	0
Aluminum	ppm	ASTM D5185m	>20	<b>4</b>	4	5
Lead	ppm	ASTM D5185m	>40	<b>0</b>	0	0
Copper	ppm	ASTM D5185m	>330	<b>&lt;1</b>	<1	<1
Tin	ppm	ASTM D5185m	>15	<b>0</b>	<1	0
Vanadium	ppm	ASTM D5185m		<b>&lt;1</b>	0	0
White Metal	scalar	*Visual	NONE	<b>NONE</b>	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	<b>NONE</b>	NONE	NONE

## CONTAMINATION












There is no indication of any contamination in the oil.

Silicon	ppm	ASTM D5185m	>25	<b>4</b>	6	6
Potassium	ppm	ASTM D5185m	>20	<b>2</b>	<1	1
Fuel		WC Method	>5	<b>&lt;1.0</b>	<1.0	<1.0
Water		WC Method	>0.2	<b>NEG</b>	NEG	NEG
Glycol		WC Method		<b>NEG</b>	NEG	NEG
Soot %	%	*ASTM D7844	>3	<b>1.1</b>	1	1
Nitration	Abs/cm	*ASTM D7624	>20	<b>8.4</b>	7.7	8.1
Sulfation	Abs/.1mm	*ASTM D7415	>30	<b>23.1</b>	22.6	22.8
Silt	scalar	*Visual	NONE	<b>NONE</b>	NONE	NONE
Debris	scalar	*Visual	NONE	<b>NONE</b>	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	<b>NONE</b>	NONE	NONE
Appearance	scalar	*Visual	NORML	<b>NORML</b>	NORML	NORML
Odor	scalar	*Visual	NORML	<b>NORML</b>	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	<b>NEG</b>	NEG	NEG

## FLUID CONDITION

The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

Sodium	ppm	ASTM D5185m		<b>&lt;1</b>	1	<1
Boron	ppm	ASTM D5185m		<b>167</b>	245	220
Barium	ppm	ASTM D5185m		<b>0</b>	0	0
Molybdenum	ppm	ASTM D5185m		<b>82</b>	86	88
Manganese	ppm	ASTM D5185m		<b>0</b>	<1	<1
Magnesium	ppm	ASTM D5185m		<b>391</b>	416	392
Calcium	ppm	ASTM D5185m		<b>1412</b>	1355	1369
Phosphorus	ppm	ASTM D5185m	1200	<b>1022</b>	913	1000
Zinc	ppm	ASTM D5185m	1300	<b>1203</b>	1125	1257
Sulfur	ppm	ASTM D5185m	3200	<b>2894</b>	2934	3433
Oxidation	Abs/.1mm	*ASTM D7414	>25	<b>15.3</b>	14.9	15.4
Base Number (BN)	mg KOH/g	ASTM D2896	9.6	<b>6.1</b>	6.2	6.6
Visc @ 100°C	cSt	ASTM D445	15.7	<b>13.3</b>	13.9	14.1



Certificate L2367

**Laboratory** : WearCheck USA - 501 Madison Ave., Cary, NC 27513  
**Sample No.** : DC0037505 **Received** : 12 Jul 2024  
**Lab Number** : 06234645 **Tested** : 15 Jul 2024  
**Unique Number** : 11123479 **Diagnosed** : 15 Jul 2024 - Wes Davis  
**Test Package** : MOB 1 ( Additional Tests: TBN )

**KELLER BUS**  
 4472 GALLANT GREEN RD  
 WALDORF, MD  
 US 20601  
 Contact: Paul Or Larry  
 Lking@kellerbus.com  
 T: (301)645-5734  
 F:

To discuss this sample report, contact Customer Service at 1-800-237-1369.  
 \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.  
 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)