WEAR CONTAMINATION FLUID CONDITION

NORMAL NORMAL


Ascendum Machinery


VOLVO SD115B R-04 (S/N 236316)


Right Wheel Hub


VOLVO PREMIUM GEAR OIL 85W-140 GL-5 (--- GAL)

VOLVO PREMIUM GEAR OIL 85W-140 GL-5 (-							
RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Resample at the next service interval to monitor.	Sample Number		Client Info		ASC0009707		
	Sample Date		Client Info		12 Jul 2024		
	Machine Age	hrs	Client Info		3008	2011	
	Oil Age	hrs	Client Info		997	2011	
	Filter Age	hrs	Client Info		0	0	
	Oil Changed		Client Info		Changed	Changed	
	Filter Changed		Client Info		None	N/A	
	Sample Status				NORMAL	NORMAL	
WEAR	Iron	ppm	ASTM D5185m	>500	156	345	
	Chromium	ppm	ASTM D5185m		<1	3	
All component wear rates are normal.	Nickel	ppm	ASTM D5185m		0	<1	
	Titanium	ppm	ASTM D5185m		<1	<1	
	Silver	ppm	ASTM D5185m		0	<1	
	Aluminum	ppm	ASTM D5185m	>5	0	1	
	Lead	ppm	ASTM D5185m	>5	0	0	
	Copper	ppm	ASTM D5185m	>50	0	<1	
	Tin	ppm	ASTM D5185m		0	<1	
	Vanadium	ppm	ASTM D5185m		0	0	
	White Metal	scalar	*Visual	NONE	NONE	MODER	
	Yellow Metal	scalar	*Visual	NONE	NONE	NONE	
CONTAMINATION	Silicon		ASTM D5185m	. 05	10	18	
	Potassium	ppm	ASTM D5185m		<1	0	
There is no indication of any contamination in the oil.	Water	ppm	WC Method		NEG	NEG	
	Silt	scalar	*Visual	NONE	LIGHT	NONE	
	Debris	scalar	*Visual	NONE	NONE	NONE	
	Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	
	Appearance	scalar	*Visual	NORML	NORML	NORML	
	Odor	scalar	*Visual	NORML	NORML	NORML	
	Emulsified Water		*Visual	>0.2	NEG	NEG	
ELUD CONDITION							
FLUID CONDITION	Sodium	ppm	ASTM D5185m		5	2	
The condition of the oil is acceptable for the time in service.	Boron	ppm	ASTM D5185m		129	150	
	Barium	ppm	ASTM D5185m		0	2	
	Molybdenum	ppm	ASTM D5185m		0	<1	
	Manganese	ppm	ASTM D5185m		3	9	
	Magnesium	ppm	ASTM D5185m		0	0	
	Calcium	ppm	ASTM D5185m		52	145	
	Phosphorus	ppm	ASTM D5185m		961	952	
	Zinc	ppm	ASTM D5185m		47	167	
	Sulfur	ppm	ASTM D5185m		27990	25056	
	Visc @ 40°C	cSt	ASTM D445		239	133	











Certificate L2367

Report Id: CARCONVC [WUSCAR] 06236616 (Generated: 07/16/2024 11:37:16) Rev: 1

Laboratory Sample No.

: ASC0009707 Lab Number : 06236616 Unique Number : 11125450 Test Package : CONST

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 15 Jul 2024

Tested : 16 Jul 2024 Diagnosed : 16 Jul 2024 - Wes Davis **CAROLINA EXCAVATING**

1036 BRANCHVIEW DR, SUITE 106 CONCORD, NC

US 28025 Contact: KEVIN LADGERWOOD

kevin@carlinaexcavation.com

T:

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: