



[578360 T AND K] VOLVO A45G 352823

Brake Cooling System

## VOLVO SUPER WET BRAKE TRANSAXLE OIL WB102 (--- GAL)

RECOMMENDATION	Test	UOM	Method	Limit/Abn	Current	History1	History2
Resample at the next service interval to monitor.	Sample Number		Client Info		VCP446352		
	Sample Date		Client Info		10 Jun 2024		
	Machine Age	hrs	Client Info		4183		
	Oil Age	hrs	Client Info		4183		
	Filter Age	hrs	Client Info		0		
	Oil Changed		Client Info		Not Changd		
	Filter Changed		Client Info		Changed		
	Sample Status				NORMAL		
WEAR	Iron	ppm	ASTM D5185m		34		
All component wear rates are normal.	Chromium	ppm	ASTM D5185m		1		
	Nickel	ppm	ASTM D5185m	>10	5		
	Titanium	ppm	ASTM D5185m		<1		
	Silver	ppm	ASTM D5185m		0		
	Aluminum	ppm	ASTM D5185m		2		
	Lead	ppm	ASTM D5185m		0		
	Copper	ppm	ASTM D5185m		145		
	Tin	ppm	ASTM D5185m	>20	0		
	Vanadium	ppm	ASTM D5185m		0		
	White Metal	scalar	*Visual	NONE	NONE		
	Yellow Metal	scalar	*Visual	NONE	NONE		
CONTAMINATION	Silicon	ppm	ASTM D5185m	>50	17		
There is no indication of any contamination in the oil.	Potassium	ppm	ASTM D5185m		2		
	Water		WC Method	>0.2	NEG		
	Silt	scalar	*Visual	NONE	NONE		
	Debris	scalar	*Visual	NONE	NONE		
	Sand/Dirt	scalar	*Visual	NONE	NONE		
	Appearance	scalar	*Visual	NORML	NORML		
	Odor	scalar	*Visual	NORML	NORML		
	Emulsified Water	scalar	*Visual	>0.2	NEG		
FLUID CONDITION	Sodium	ppm	ASTM D5185m		6		
The condition of the oil is acceptable for the time in service.	Boron	ppm	ASTM D5185m		118		
	Barium	ppm	ASTM D5185m		0		
	Molybdenum	ppm	ASTM D5185m		<1		
	Manganese	ppm	ASTM D5185m		1		
	Magnesium	ppm	ASTM D5185m		20		
	Calcium	ppm	ASTM D5185m		3364		
	Phosphorus	ppm	ASTM D5185m		1234		
	Zinc	ppm	ASTM D5185m		1462		
	Sulfur	ppm	ASTM D5185m		4619		


Visc @ 40°C


cSt

ASTM D445 55

Contact/Location: KENNY HANEY - VOLVO0093

43.7





ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC Laboratory : WearCheck USA - 501 Madison Ave., Cary, NC 27513 Sample No. Received 8418 PALM RIVER ROAD : VCP446352 : 16 Jul 2024 Lab Number : 06238206 Tested : 17 Jul 2024 Diagnosed Unique Number : 11127040 : 18 Jul 2024 - Sean Felton Test Package : MOB 1 Contact: KENNY HANEY Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369. khaney@flaglerce.com \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. T: (813)630-0077 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (813)630-2233

Contact/Location: KENNY HANEY - VOLVO0093

TAMPA, FL

US 33619