

# LABORATORY ANALYSIS



11525 Rock Island Court, St. Louis, MO 63043  
Tel: 1-800-876-0008 info@englube.com

**EGS MEXICO S DE RL DE CV**  
VIA MONTERREY MATAMOROS NO 598  
MEXICO, ZZ  
Mexico  
Contact: Lizbeth Manzanares  
Lizbeth.manzanares@emerson.com  
T:  
F:

Department **SCREW MACHINE**  
Equipment No. **176 MAZAK 1 (X0009)**  
System **Unknown Component**  
Oil Type **ENGINEERED LUBRICANTS ENCOOL SOL-3250FNF-LF (--- GAL)**

***Sample is currently in the laboratory***

**Customer Id:** ENC0005J03  
**Sample No.:** EN23100285  
**Lab Number:** 23100285  
**Test Package:** TEST



*To manage this report scan the QR code*

*To discuss the diagnosis or test data:*  
+1

*To change component or sample information:*  
Tracy Weaks +1 (314)872-9540  
[tweaks@englube.com](mailto:tweaks@englube.com)

**Sample is currently in the laboratory**



**Laboratory** : WearCheck -  
**Sample No.** : EN23100285      **Received** : 12 Oct 2023  
**Lab Number** : 23100285      **Diagnosed** :  
**Unique Number** : 16025020      **Diagnostician** :  
**Test Package** : TEST ( Additional Tests: Bacteria, Hardness, RatioRefrac, TrampCuffSediment )  
*To discuss this sample report, contact Customer Service at 1-800-268-2131.*  
*Test denoted (\*) outside scope of accreditation, (m) method modified, (e) tested at external lab.*  
*Validity of results and interpretation are based on the sample and information as supplied.*

EGS  
VIA M  
MEXI  
Mexic  
Conta  
Lizbe  
T:  
F: