

# LABORATORY ANALYSIS



11525 Rock Island Court, St. Louis, MO 63043  
Tel: 1-800-876-0008 info@englube.com

**COPELAND (MHDS)**  
6001 S. 35TH STREET, SUITE D"  
REYNOSA, ZZ  
US  
Contact: GERARDO GUERRERO  
francisco.castillo@Copeland.com  
T:  
F:

Department **REYLAM - DIECAST**  
Equipment No. **CEL 5 OKUMA 2 (X0088)**  
System **Coolant**  
Oil Type **ENGINEERED LUBRICANTS ENCOOL SOL-6465GF-ND-XL-RO (--- GAL)**

## DIAGNOSIS

The fluid is suitable for further service. Resample at the next service interval to monitor. All metal levels are normal indicating no corrosion in the cooling system. There is no indication of any contamination in the coolant.

## SAMPLE INFORMATION

Lab Number	New	<b>2312-00648</b>	---	---
Date of Sample	(Typical)	<b>13 Dec 2023</b>	---	---
Oil Added		<b>UNK</b>	---	---
Last Drain Date		<b>--</b>	---	---
Last Filter Service		<b>--</b>	---	---
Sample Point		<b>---</b>	---	---
Sample Status		<b>NORMAL</b>	---	---

## RATIO PER REFRACTOMETER

Refract. Reading		<b>13.3</b>	---	---
Refract. Model		<b>DIGITAL</b>	---	---
Refract. Ratio	oil:water	<b>1.5:1</b>	---	---

**Customer Id:** MOTMCA  
**Sample No.:** EN23120648  
**Lab Number:** 23120648  
**Test Package:** TEST



To manage this report scan the QR code

To discuss the diagnosis or test data:  
Brian Klutenkamper +1 (314)872-9540  
[bklutenkamper@englube.com](mailto:bklutenkamper@englube.com)

To change component or sample information:  
Tracy Weaks +1 (314)872-9540  
[tweaks@englube.com](mailto:tweaks@englube.com)

# OIL ANALYSIS REPORT

