

LABORATORY ANALYSIS



11525 Rock Island Court, St. Louis, MO 63043
Tel: 1-800-876-0008 info@englube.com

WOODWARD CORPORATION
6300 WEST HOWARD STREET
NILES, IL
United States 60714
Contact: Daniel Aviles
daniel.aviles@woodward.com
T:
F:

Department **NPI OILS**
Equipment No. **1933 CNC MILLING MACHINE (00015)**
System **Unknown Component**
Oil Type **ENGINEERED LUBRICANTS ENSPIN 1155-LAW-PF (--- GAL)**

Diagnosis

All conditions are GREEN. Continue use of oil and filter element at this time.

Sample Information

Lab Number	New	2403-00531	2311-00547	2308-00180
Date of Sample	(Typical)	14 Mar 2024	16 Nov 2023	03 Aug 2023
Oil Added		UNK	UNK	UNK
Last Drain Date		--	--	--
Months on Sample		188.8	185.0	181.7
Last Filter Service		--	--	--
Sample Point		---	---	---
Sample Status		NORMAL	NORMAL	NORMAL

ICP - OILS (REPORTED IN PARTS PER MILLION)

Aluminum (Al)	ppm	*	<5	<5
---------------	-----	---	----	----

Contamination

Water		NEG	NEG	NEG
-------	--	------------	-----	-----

Customer Id: ENC0658001
Sample No.: EN24030531
Lab Number: 24030531
Test Package: TEST



To manage this report scan the QR code

To discuss the diagnosis or test data:

Beau Vuagniaux +1
bvuagniaux@englube.com

To change component or sample information:

Tracy Weaks +1 (314)872-9540
tweaks@englube.com

OIL ANALYSIS REPORT