



NEW SYSTEM

Customer: PTRHTF30115	System Information	Sample Information
BI-AX INTERNATIONAL INC	System Volume: 400 ltr	Lab No: 02216883
596 CEDAR ST	Bulk Operating Temp: Not Specified	Analyst: Lynn Billings
WINGHAM, ON N0G 2W0 Canada	Heating Source:	Sample Date: 05/15/18
Attn:	Blanket:	Received Date: 05/17/18
Tel: (519)357-1818	Fluid: PETRO CANADA CALFLO AF	Completed: 05/25/18
E-Mail:	Make:	To discuss this report contact Lynn
		Billings at (289)523-0262


Recommendation: this samples exhibits a large amount of water (4.5%). It is also an ISO 22 which Petro-Canada does not carry. It has more iron and sulfur than the other sample. The GCD is marginally high and the 10% distillation point is low. This fluid should be removed from the system and the system should be drained, cleaned and flushed before addition of new fluid.

Comments: Water contamination levels are severely high. Water contamination levels are severely high.. ppm Water contamination levels are severely high. Insufficient sample was received to conduct all the routine laboratory tests. (GCD) % < 335°C is marginally high. (GCD) 10% Distillation Point is marginally low.





Report ID: [02216883] (Generated: 05/25/2018 17:48:06) - Page 1 - Copyright 2018 Wearcheck Inc. All Rights Reserved.



Petro-Canada makes no representation or warranty of any kind, either express or implied, as to the accuracy or completeness of the analysis and assumes no responsibility and shall have no liability whatsoever with respect to such analysis, or a party's use of it. Petro-Canada is a division of HollyFrontier Corporation.

Report ID: [02216883] (Generated: 05/25/2018 17:48:06) - Page 2 - Copyright 2018 Wearcheck Inc. All Rights Reserved.