

## **LN01 Filled Sealdown Hot Oil System**

## Customer: PTRHTF10141

TAMKO BUILDING PRODUCTS

2300 35TH ST

TUSCALOOSA, AL 35401 USA

Attn: Eric Foote

Tel: x:

E-Mail: eric foote@tamko.com

## System Information

System Volume: 110 gal

Bulk Operating Temp: 425F / 218C

**Heating Source:** 

Blanket:

Fluid: PETRO CANADA CALFLO HTF

Make: Heat Exchanger And T

## Sample Information


Lab No: 02475745 Analyst: Jake Finn Sample Date: 02/25/22 Received Date: 03/07/22 Completed: 03/09/22


Jake Finn

jake.finn@hollyfrontier.com

Recommendation: Sample indicates no signs of wear, contamination or fluid degradation. This fluid is suitable for continued use, please resample and submit for testing in 12 months.


Comments: N/A







Elemental analysis results (above) in parts per million (ppm). [10,000 ppm = 1.0%]



Historical Comments	
09/15/21	Sample indicates no signs of wear, contamination or fluid degradation. This fluid is suitable for continued use, please resample and submit for testing in 12 months.N/A
03/24/21	Sample indicates no signs of wear, contamination or fluid degradation. This fluid is suitable for continued use, please resample and submit for testing in 12 months.N/A
10/30/20	Fluid appears to be in good condition and is suitable for continued use. Please resubmit for testing in 12 months.
08/06/20	GCD 10% distillation point has improved from last sample. Oil appears to be in great condition and is suitable for continued use. Please resubmit sample for testing in one year. Very light debris noted by lab.

Petro-Canada makes no representation or warranty of any kind, either express or implied, as to the accuracy or completeness of the analysis and assumes no responsibility and shall have no liability whatsoever with respect to such analysis, or a party's use of it. Petro-Canada is a division of HollyFrontier Corporation.