


CONDYLINEHEATER


Customer: PTRHTF20191	System Information	Sample Information
STRATHCONA RESOURCES	System Volume: 35000 ltr	Lab No: 02622154
06-08-62-03W6	Bulk Operating Temp: 266F / 130C	Analyst: Clinton Buhler
PO BOX 25269 WAPITI CENTRE	Heating Source:	Sample Date: 02/18/24
GRANDE PRAIRIE, AB T8W 0G2 CA	Blanket:	Received Date: 03/14/24
Attn: Ken Irving	Fluid: PETRO CANADA PETRO-THERM	Completed: 03/18/24
Tel: (250)361-6180	Make: RUSHTON	Clinton Buhler
E-Mail:		Clinton.Buhler@HFSinclair.com

Recommendation: Sample results indicate the fluid is in suitable condition for continued service. Please re-sample in 12 months (please wait 12 months unless there is system upset or contamination).


Comments:

Sample Date	Received Date	Fluid Age	Sample Location	Flash Point (COC)	Water (KF)	Viscosity (40°C)	Acid Number	Solids	GCD 10%	GCD 50%	GCD 90%	GCD % < 335°C
	mm/dd/yy			°F/°C	ppm	cSt	mg/KOH/ g	%wt	°F/°C	°F/°C	°F/°C	%
02/18/24	03/14/24	0.0m		424 / 218	14	34.0	0.02	0.036	715 / 379	811 / 433	911 / 489	2.58
08/21/23	09/05/23	0.0m		432 / 222	23.2	34.2	0.03	0.038	726 / 386	813 / 434	911 / 488	1.03
06/02/21	06/08/21	24.0m	discharge pump	421 / 216	15.6	33.8	0.02	0.042	712 / 378	798 / 426	904 / 485	1.97
05/23/21	06/08/21	24.0m	Condy line heater	403 / 206	17.1	33.8	0.02	0.062	709 / 376	804 / 429	897 / 481	2.81
02/23/21	03/05/21	24.0m	off pump	424 / 218	9.1	32.7	0.02	0.044	725 / 385	814 / 435	915 / 490	1.25






Flash Point (°C)



720 / 382 817 / 436 900 / 482 1.00



250°C

150°C

100°C

2,000

0

ഗശ

8 0 1

Historical Comments

0.5

0

Jul12/16

Jan23/17

0ct12/17

0ct12/18

Feb23/21

Jun2/21

Feb18/24

08/21/23	Sample results indicate the fluid is in suitable condition for continued service. Please re-sample in 12 months.
06/02/21	Sample results indicate that the fluid is in suitable condition for continued service. Please re-sample in 12 months.
05/23/21	Sample results indicate that the fluid is in suitable condition for continued service. Please re-sample in 12 months.
02/23/21	Sample results indicate that the fluid is in suitable condition for continued service. Please re-sample in 12 months

Petro-Canada makes no representation or warranty of any kind, either express or implied, as to the accuracy or completeness of the analysis and assumes no responsibility and shall have no liability whatsoever with respect to such analysis, or a party's use of it. Petro-Canada is a division of HollyFrontier Corporation.