





## HOH 2

## **Customer:**

ASSOCIATED ASPHALT 195 LAWSON FORK ROAD INMAN, SC 29349 USA Attn: JESSICA HALFORD

Tel:

E-Mail: JHALFORD@ASSOCIATEDASP

HALT.COM

## System Information

System Volume: 2000 gal

Bulk Operating Temp: Not Specified

Heating Source:

Blanket: Fluid: N/A Make: CEJ

## Sample Information

Lab No: 05744355 Analyst: Doug Bogart Sample Date: 01/18/23 Received Date: 01/19/23 Completed: 01/25/23

Doug Bogart

dougb@wearcheckusa.com

Recommendation: This is a baseline read-out on the submitted sample.

Comments: All metal levels are normal indicating no corrosion in the system. There is no indication of any contamination in the sample. The condition of the sample is suitable for further service.



Report ID: [05744355] (Generated: 01/25/2023 12:29:14) - Page 1 - Copyright 2023 Wearcheck Inc. All Rights Reserved.





Elemental analysis results (above) in parts per million (ppm). [10,000 ppm = 1.0%]

GCD Spectrum

Historical Comments	
12/06/19	This is a baseline read-out on the submitted sample. There is no indication of any contamination in the sample. The condition of the sample is suitable for further service.
01/31/19	This is a baseline read-out on the submitted sample. There is no indication of any contamination in the sample. The condition of the sample is suitable for further service.

WearCheck Canada makes no representation or warranty of any kind, either express or implied, as to the accuracy or completeness of the analysis and assumes no responsibility and shall have no liability whatsoever with respect to such analysis, or a party's use of it.