

LIEBHERR

CONSTRUCTION EQUIPMENT



LIEBHERR LH50M 097459-1216 - Front Right Wheel Hub

Sample No: LH0230416

Oil Type: PETRO CANADA TRAXON 75W90 SYNTHETIC



SAMPLE INFORMATION

Sample Number	LH0230416	LH0183922	LH0194668	LH0194641
Sample Date	05 May 2022	05 May 2022	29 Oct 2021	25 Jul 2021
Machine Hours	22049	22049	20093	18995
Oil Hours	0	0	0	0
Oil Changed	Changed	Changed	Changed	Not Changd
Sample Status	NORMAL	NORMAL	NORMAL	NORMAL

J.D. Irving

Truro Sawmill, 529 Valley Dale Road
Truro, NS
CA B2N 5C5
Contact: Sheldon Richardson
richardson.sheldon@jdირving.com
T: (902)890-9419
F:



OIL CONDITION

Visc @ 40°C	cSt	97.9	87.8	93.4	92.3
-------------	-----	------	------	------	------



CONTAMINATION

Silicon	ppm	2	4	2	2
Sodium	ppm	0	1	1	2
Potassium	ppm	<1	<1	<1	<1



WEAR METALS

Iron	ppm	25	48	36	33
Copper	ppm	<1	7	5	5
Lead	ppm	0	<1	<1	0
Tin	ppm	0	0	<1	0
Aluminum	ppm	0	<1	<1	<1
Chromium	ppm	0	<1	<1	<1
Molybdenum	ppm	0	<1	<1	<1
Nickel	ppm	<1	<1	<1	<1
Titanium	ppm	0	0	0	0
Silver	ppm	0	0	0	0
Manganese	ppm	<1	<1	<1	<1
Vanadium	ppm	0	0	0	0



ADDITIVES

Calcium	ppm	7	14	18	18
Magnesium	ppm	2	3	4	4
Zinc	ppm	7	17	16	16
Phosphorus	ppm	1316	1316	1397	1317
Barium	ppm	0	0	0	0
Boron	ppm	320	314	339	310

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: JDITRU
Unique No: 5409262
Signed: Kevin Marson
Report Date: 02 Jun 2022



GRAPHS

