

LIEBHERR A924C 064062-1049 - Front Right Wheel Hub

Sample No: LH0260988

PETRO CANADA TRAXON 75W90 SYNTHETIC **Oil Type:**

0 107

5				
SAMPLE INFORMATION				
Sample Number	LH0260988	LH0185892		
Sample Date	14 Jun 2023	08 Jan 2021		
Machine Hours	13298	10412		
Oil Hours	0	0		
Oil Changed	Not Changd	Not Changd		
Sample Status	NORMAL	NORMAL		

Visc @ 40°C

OIL CONDITION cSt

	NTAMINA	TION		
Silicon	ppm	03	0 4	
Sodium	ppm	07	08	
Potassium	ppm	○ <1	◯ <1	
-				

0 112

A				
WE/	AR META	LS		
Iron	ppm	0 78	● 60	
Copper	ppm	0 11	0 8	
Lead	ppm	() <1	○ <1	
Tin	ppm	0	0	
Aluminum	ppm	◯ <1	○ <1	
Chromium	ppm	<mark>○</mark> <1	○ <1	
Molybdenum	ppm	0	○ <1	
Nickel	ppm	○ <1	○ <1	
Titanium	ppm	0	0	
Silver	ppm	0	<1	
Manganese	ppm	01	○ <1	
Vanadium	mag	0	0	

0 **ADDITIVES** Calcium 264 338 ppm 02 Magnesium ppm 03 Zinc 146 0 118 ppm 0 1516 Phosphorus 0 1501 ppm Barium ppm 2 02 Boron 0 149 ppm 0 172





MARCEL DUVAL FER ET METAUX INC. 661 RANG STE-MARIE ST. SEBASTIEN, QC CA J0J 2C0

Contact: Service Manager

T: F:

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:	MARSTS
Unique No:	5604444
Signed:	Wes Davis
Report Date:	29 Jun 2023

Report Id: MARSTS [WCAMIS] 02567398 (Generated: 07/03/2023 16:34:45) Rev: 1


Submitted By: Eric Leblond





GRAPHS

 \odot



Report Id: MARSTS [WCAMIS] 02567398 (Generated: 07/03/2023 16:34:48) Rev: 1