LIEBHERR

CONSTRUCTION EQUIPMENT

[(362420)] LIEBHERR L580 065390-1760 - Diesel Engine

Sample No: LH0218118

Oil Type: SHELL ROTELLA T6 5W40

_				
U SAM	PLE INF	ORMATION		
Sample Number		LH0218118	LH0218115	
Sample Date		12 May 2023	13 Feb 2023	
Machine Hours		1331	700	
Oil Hours		0	0	
Oil Changed		Changed	Changed	
Sample Status		NORMAL	NORMAL	
OIL	ONDITI	ON		
Visc @ 100°C	cSt	13.4	O 12.3	
Oxidation (PA)	%	84	188	
-4				
CON	TAMIN/	ATION		
Soot %	%	0	0	
Nitration (PA)	%	71	94	
Sulfation (PA)	%	64	109	
Glycol	%	NEG	NEG	
Fuel	%	<1.0	0.7	
Silicon	ppm	13	O 9	
Sodium	ppm	2	O 2	
Potassium	ppm	3	O 2	

METALS				
ppm	6	O 9		
ppm	165	O 257		
ppm	4	8		
ppm	O <1	O <1		
ppm	2	O 2		
ppm	O <1	O <1		
ppm	5	41		
ppm	○ <1	0		
ppm	<1	O <1		
ppm	0	0		
ppm	() <1	O 2		
ppm	0	0		
	ppm	ppm	ppm	ppm

ADDITIVES								
Calcium	ppm	1976	O 1533					
Magnesium	ppm	180	O 823					
Zinc	ppm	1103	911					
Phosphorus	ppm	937	O 857					
Barium	ppm	5	O 22					
Boron	ppm	104	O 95					



HUBERT & FILS
474 ROUTE 105
BOIS-FRANC, QC
CA J9E 3A9
Contact: Eric Brisebois
ericbrisebois99@gmail.com

F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: HUBBOI
Unique No: 5604584
Signed: Wes Davis
Report Date: 30 Jun 2023

LIEBHERR







GRAPHS

