

LIEBHERR LH26M 142537-1252 - Splitter Box

51.8

210/

Sample No: LH0259689

Oil Type: LIEBHERR 75W90

SAMPLE INFORMATION

Sample Number	LH0259689	 	
Sample Date	14 Jun 2023	 	
Machine Hours	500	 	
Oil Hours	0	 	
Oil Changed	Changed	 	
Sample Status	NORMAL	 	

OIL CONDITION

Visc @ 40°C

a4

-

cSt

	TAMINA	TION		
Silicon	ppm	04	 	
Sodium	ppm	0 41	 	
Potassium	ppm	0 40	 	

A				
WE/	AR META	LS		
Iron	ppm	0 11	 	
Copper	ppm	0 16	 	
Lead	ppm	○ .0	 	
Tin	ppm	○ <1	 	
Aluminum	ppm	03	 	
Chromium	ppm	<1	 	
Molybdenum	ppm	2	 	
Nickel	ppm	<u> </u>	 	
Titanium	ppm	<1	 	
Silver	ppm	0	 	
Manganese	ppm	19	 	
Vanadium	ppm	<1	 	



ADDITIVES

Galcium	ppm	3194	 	
Magnesium	ppm	10	 	
Zinc	ppm	1073	 	
Phosphorus	ppm	1072	 	
Barium	ppm	1	 	
Boron	ppm	5	 	





9428-7158 QC INC. 935 ROUTE SHENLEY EST ST-HONORE DE SHENLEY, QC CA GOM 1V0 Contact: Service Manager

T: F:

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:	942S
Unique No:	5605
Signed:	Kevir
Report Date:	05 Ju


STH 5087 n Marson ul 2023





GRAPHS

 \odot



Report Id: 942STH [WCAMIS] 02568041 (Generated: 07/07/2023 14:13:20) Rev: 1