LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR L586 21066 - Front Right Wheel Hub

Sample No: LH0186875

Magnesium

Phosphorus

Zinc

Barium

Boron

Oil Type: GEAR OIL SAE 80

Sample Number		LH0186875	LH0162860		
Sample Date		06 Jul 2023	09 May 2022		
Machine Hours		18165	0		
Oil Hours		0	0		
Oil Changed		Changed	N/A		
Sample Status		NORMAL	NORMAL		
<u> </u>					
OIL	ONDITIONO	ON			
/isc @ 40°C	cSt	90.9	O 87.1		
CON	TAMINA	ATION			
Silicon	ppm	4	5		
Sodium	ppm	1	O 1		
Potassium	ppm	1	10		
	R META		O 54		
PQ			O 54		
ron	ppm	O 701	O 914		
Copper	ppm	0 7	0 8		
_ead	ppm	01	0 1		
Γin 	ppm	0 0	0 <1		
Aluminum	ppm	01	0 2		
Chromium	ppm	01	0 2		
Molybdenum	ppm	0 0	0 <1		
Nickel	ppm	() <1	0 1		
Γitanium	ppm	0	0	***	
Silver	ppm	0	0	***	
Manganese	ppm	0 7	0 9	***	
/anadium	ppm	0	0		
ADD	ITIVES				
Calcium	ppm	19	0 8		
	F F				

0 8

0

197



CLOUTHIER VENTURES LTD.

59 MATTHEWS STREET, R.R. # 5 PEMBROKE, ON

CA K8A 0A6

Contact: Travis Bennett tbennett@clouthierconst.com

T: (613)735-6531 F: (613)735-2769

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: CLOPEM
Unique No: 5607266
Signed: Wes Davis
Report Date: 14 Jul 2023

01

13

0

Report Id: CLOPEM [WCAMIS] 02570220 (Generated: 07/14/2023 14:35:55) Rev: 1

139

1270

ppm

ppm

ppm

ppm

ppm

LIEBHERR







GRAPHS

