LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR LH30M 139284-1253 - Rear Right Wheel Hub

Sample No: LH0208260

Oil Type: LIEBHERR GEAR BASIC 90 LS

SAMPLEINFORMATION									
Sample Number		LH0208260	LH0241867						
Sample Date		07 Jun 2023	18 Apr 2023						
Machine Hours		1668	1142						
Oil Hours		0	0						
Oil Changed		Changed	Changed						
Sample Status		NORMAL	NORMAL						
OIL CONDITION									
Visc @ 40°C	cSt	176	100						
CONTAMINATION									
Silicon	ppm	2	O <1						
Sodium	ppm	2	02						
Potassium	ppm	() <1	0						

()				
WEA	R META	LS		
Iron	ppm	0 7	3	
Copper	ppm	○ <1	O <1	
Lead	ppm	0	O 0	
Tin	ppm	0	0	
Aluminum	ppm	() <1	O 0	
Chromium	ppm	0	O 0	
Molybdenum	ppm	0	O 0	
Nickel	ppm	() <1	O <1	
Titanium	ppm	0	0	
Silver	ppm	0	0	
Manganese	ppm	() <1	O <1	
Vanadium	ppm	0	0	

ADDITIVES								
Calcium	ppm	102	O 162					
Magnesium	ppm	1	O 0					
Zinc	ppm	33	159					
Phosphorus	ppm	2238	1308					
Barium	ppm	0	0 0					
Boron	ppm	17	102					



HUBERT & FILS 474 ROUTE 105 BOIS-FRANC, QC CA J9E 3A9 Contact: Eric Brisebois ericbrisebois99@gmail.com

T: F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:HUBBOIUnique No:5607765Signed:Wes DavisReport Date:18 Jul 2023

LIEBHERR







GRAPHS

