

LIEBHERR

CONSTRUCTION EQUIPMENT



LIEBHERR LH30M 139284-1253 - Rear Left Wheel Hub

Sample No: LH0208259

Oil Type: LIEBHERR GEAR BASIC 90 LS



HUBERT & FILS

474 ROUTE 105
BOIS-FRANC, QC
CA J9E 3A9

Contact: Eric Brisebois
ericbrisebois99@gmail.com

T:
F:



SAMPLE INFORMATION

Sample Number	LH0208259	LH0241866	---	---
Sample Date	06 Jul 2023	18 Apr 2023	---	---
Machine Hours	1668	1142	---	---
Oil Hours	0	0	---	---
Oil Changed	Changed	Changed	---	---
Sample Status	NORMAL	NORMAL	---	---



OIL CONDITION

Visc @ 40°C	cSt	175	99.9	---	---
-------------	-----	-----	------	-----	-----



CONTAMINATION

Silicon	ppm	2	<1	---	---
Sodium	ppm	2	1	---	---
Potassium	ppm	<1	<1	---	---



WEAR METALS

Iron	ppm	7	3	---	---
Copper	ppm	<1	1	---	---
Lead	ppm	0	0	---	---
Tin	ppm	0	0	---	---
Aluminum	ppm	<1	0	---	---
Chromium	ppm	0	0	---	---
Molybdenum	ppm	0	0	---	---
Nickel	ppm	<1	<1	---	---
Titanium	ppm	0	0	---	---
Silver	ppm	0	0	---	---
Manganese	ppm	<1	<1	---	---
Vanadium	ppm	0	0	---	---



ADDITIVES

Calcium	ppm	97	154	---	---
Magnesium	ppm	1	<1	---	---
Zinc	ppm	32	157	---	---
Phosphorus	ppm	2282	1302	---	---
Barium	ppm	<1	0	---	---
Boron	ppm	17	101	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: HUBBOI
Unique No: 5607768
Signed: Wes Davis
Report Date: 18 Jul 2023



GRAPHS

