

## LIEBHERR LH50M 142304-1216 - Rear Left Wheel Hub

Sample No: LH0248057

**Oil Type:** LIEBHERR GEAR BASIC 90 LS

## **SAMPLE INFORMATION**

Sample Number	LH0248057	 	
Sample Date	25 Jul 2023	 	
Machine Hours	3000	 	
Oil Hours	0	 	
Oil Changed	Changed	 	
Sample Status	NORMAL	 	

**OIL CONDITION** 

Visc @ 40°C

cSt 0 187

	TAMIN	ATION	
Silicon	ppm	<b>5</b>	
Sodium	ppm	03	
Potassium	ppm	◯ <1	

WEA	<b>R METALS</b>			
Iron	ppm	0 86	 	
Copper	ppm	0 14	 	
Lead	ppm	<b>○</b> <1	 	
Tin	ppm	0 🔘	 	
Aluminum	ppm	<b>○</b> <1	 	
Chromium	ppm	<b>○</b> <1	 	
Molybdenum	ppm	0	 	
Nickel	ppm	0	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	01	 	
Vanadium	ppm	0	 	

	DITIVES			
Calcium	ppm	23	 	
Magnesium	ppm	<b>○</b> <1	 	
Zinc	ppm	21	 	
Phosphorus	ppm	0 2343	 	
Barium	ppm	0	 	
Boron	ppm	<b>3</b>	 	





**PRODUITS FORESTIERS D.G. LTEE** 313 RANG ST-JOSEPH STE-AURELIE, QC CA GOM 1M0

Contact: Roger .

T: (418)593-3547 F: (418)593-3633

## Diagnosis

Confirm the source of the lubricant being utilized for top-up/fill. Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. Additive levels indicate the addition of a different brand, or type of oil. The condition of the oil is acceptable for the time in service.

Depot: Unique No: Signed: **Report Date:** 

PRO9STE 5618106 Wes Davis 28 Jul 2023

Submitted By: ?





GRAPHS

 $\odot$ 

