LIEBHERR

CONSTRUCTION EQUIPMENT

[[569848]] LIEBHERR HS835 182294 - 2 Winch

Sample No: LH0266100

Oil Type: PETRO CANADA TRAXON 75W90 SYNTHETIC

SAMPLEIN	FORMATION		
Sample Number	LH0266100	 	
Sample Date	21 Jul 2023	 	
Machine Hours	21025	 	
Oil Hours	0	 	
Oil Changed	N/A	 	
Sample Status	ABNORMAL	 	



HIGGS & HIGGS RR # 4 ST THOMAS, ON CA N5P 3S8 Contact: Bernie Higgs

T: (519)631-4095 F: (519)631-2745

OIL CC	NDITION				
40°C	cSt	89.8			

	CONT	CONTAMINATION					
Silicon		ppm	13				

Silicon	ppm	13	 	
Sodium	ppm	2	 	
Potassium	ppm	() <1	 	

WEA	AR META	LS		
PQ		36	 	
Iron	ppm	189	 	
Copper	ppm	O <1	 	
Lead	ppm	0	 	
Tin	ppm	0	 	
Aluminum	ppm	3	 	
Chromium	ppm	2	 	
Molybdenum	ppm	○ <1	 	
Nickel	ppm	() <1	 	
Titanium	ppm	1	 	
Silver	ppm	0	 	
Manganese	ppm	1	 	
Vanadium	ppm	0	 	
THE RESERVE OF THE PERSON NAMED IN COLUMN 1				

Diagnosis

We advise that you check for visible metal particles in the oil. We recommend that you drain the oil from the component if this has not already been done. We recommend an early resample to monitor this condition. Moderate concentration of visible metal present. Gear wear is indicated. There is no indication of any contamination in the oil. The oil is no longer serviceable as a result of the abnormal and/or severe wear.

Q				
	A	DD	ITIV	ES

ADDITIVES					
Calcium	ppm	34			
Magnesium	ppm	3			
Zinc	ppm	39			
Phosphorus	ppm	1383			
Barium	ppm	2			
Boron	ppm	252			

Depot:HIGSTTUnique No:5618115Signed:Kevin MarsonReport Date:02 Aug 2023

LIEBHERR

CONSTRUCTION EQUIPMENT





GRAPHS

