

# LIEBHERR

## CONSTRUCTION EQUIPMENT



### LIEBHERR LH30M 73579-1200 - Splitter Box

Sample No: LH0270353

Oil Type: PETRO CANADA TRAXON 75W90 SYNTHETIC



**LIEBHERR CANADA LTD.**  
 1015 SUTTON DRIVE  
 BURLINGTON, ON  
 CA L7L 5Z8  
 Contact: Joseph Gillis  
 joseph.gillis@liebherr.com  
 T:  
 F: (905)319-6622



#### SAMPLE INFORMATION

Sample Number	LH0270353	---	---	---
Sample Date	26 Jul 2023	---	---	---
Machine Hours	9058	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---



#### OIL CONDITION

Visc @ 40°C	cSt	● 94.0	---	---	---
-------------	-----	--------	-----	-----	-----



#### CONTAMINATION

Silicon	ppm	● 2	---	---	---
Sodium	ppm	● 3	---	---	---
Potassium	ppm	● <1	---	---	---



#### WEAR METALS

Iron	ppm	● 7	---	---	---
Copper	ppm	● <1	---	---	---
Lead	ppm	● 0	---	---	---
Tin	ppm	● 0	---	---	---
Aluminum	ppm	● <1	---	---	---
Chromium	ppm	● 0	---	---	---
Molybdenum	ppm	● <1	---	---	---
Nickel	ppm	● 0	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	● 0	---	---	---
Vanadium	ppm	0	---	---	---



#### ADDITIVES

Calcium	ppm	● 16	---	---	---
Magnesium	ppm	● 4	---	---	---
Zinc	ppm	● 31	---	---	---
Phosphorus	ppm	● 1311	---	---	---
Barium	ppm	● 0	---	---	---
Boron	ppm	● 296	---	---	---

#### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: LIEMIS  
 Unique No: 5618873  
 Signed: Wes Davis  
 Report Date: 02 Aug 2023



### GRAPHS

