

LIEBHERR

CONSTRUCTION EQUIPMENT



LIEBHERR R946 046753-1491 - Left Final Drive

Sample No: LH

Oil Type: PETRO CANADA TRAXON 75W90 SYNTHETIC



SAMPLE INFORMATION

Sample Number	LH	LH	LH	LH0192530
Sample Date	03 Aug 2023	24 Mar 2023	03 Jun 2021	25 Feb 2021
Machine Hours	9304	8383	0	0
Oil Hours	0	0	0	0
Oil Changed	N/A	Changed	Changed	Changed
Sample Status	NORMAL	NORMAL	NORMAL	NORMAL

QIT - Rio Tinto Fer et Titane Inc.

1625 Rte Marie Victorin

Sorel-Tracy, QC

CA J3R 1M6

Contact: Sebastien Fortin

Sebastien.Fortin2@riotinto.com

T:

F: (450)746-9414



OIL CONDITION

Visc @ 40°C	cSt	189	179	192	190
-------------	-----	-----	-----	-----	-----



CONTAMINATION

Silicon	ppm	2	3	2	5
Sodium	ppm	2	3	4	4
Potassium	ppm	<1	<1	<1	<1



WEAR METALS

Iron	ppm	45	74	40	68
Copper	ppm	<1	<1	<1	<1
Lead	ppm	0	0	0	0
Tin	ppm	0	0	0	0
Aluminum	ppm	1	3	1	2
Chromium	ppm	<1	<1	<1	<1
Molybdenum	ppm	0	<1	0	<1
Nickel	ppm	1	2	<1	1
Titanium	ppm	24	53	7	17
Silver	ppm	0	0	<1	<1
Manganese	ppm	<1	<1	<1	<1
Vanadium	ppm	<1	1	<1	<1



ADDITIVES

Calcium	ppm	12	14	10	20
Magnesium	ppm	6	13	2	4
Zinc	ppm	13	17	8	11
Phosphorus	ppm	2290	2418	2308	2277
Barium	ppm	<1	<1	1	<1
Boron	ppm	2	2	8	11

Diagnosis

Confirm the source of the lubricant being utilized for top-up/fill. Échantillonner de nouveau l'équipement au prochain intervalle de vidange afin d'en surveiller la condition. Les taux d'usure de tous les composants sont normaux. Il n'y a aucun indice de contamination dans l'huile. Les niveaux d'additifs indiquent l'ajout d'une autre marque ou d'un autre type d'huile. La viscosité de l'échantillon se situe dans la portée de l'SAE 90; nous vous conseillons de vérifier. L'état de l'huile est acceptable pour la durée de service.

Depot: QITGARAGE

Unique No: 5619656

Signed: Kevin Marson

Report Date: 08 Aug 2023



GRAPHS

