LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR LH30M 137424-1253 - Front Left Wheel Hub

Sample No: LH0228737

Oil Type: LIEBHERR GEAR BASIC 90 LS

5				
U SAN	APLE INFO	ORMATION		
Sample Number	r	LH0228737	LH0228725	
Sample Date		21 Jun 2023	25 Nov 2022	
Machine Hours		2000	1000	
Oil Hours		0	0	
Oil Changed		Changed	Changed	
Sample Status		NORMAL	NORMAL	
OIL	CONDITION	ON		
Visc @ 40°C	cSt	63.6	64.6	
24 C				
CON	ITAMIN#	ATION		
Silicon	ppm	8	8	
Sodium	ppm	21	O 19	
Potassium	ppm	2	0 2	

Polassium	ppm	U 2	0 2	
WEA	R METAI	LS		
Iron	ppm	51	O 43	
Copper	ppm	64	O 45	
Lead	ppm	2	O 1	
Tin	ppm	0	0	
Aluminum	ppm	1	O 1	
Chromium	ppm	1	O <1	
Molybdenum	ppm	0	O 0	
Nickel	ppm	0	O 0	
Titanium	ppm	<1	<1	
Silver	ppm	0	0	
Manganese	ppm	1	O 1	
Vanadium	ppm	0	0	
THE STATE OF THE S				

ADDITIVES									
Calcium	ppm	3510	3587						
Magnesium	ppm	10	O 9						
Zinc	ppm	1397	1386						
Phosphorus	ppm	1197	1220						
Barium	ppm	○ <1	O <1						
Boron	ppm	102	100						



CAC ENTERPRISES GROUP INC.

2411 76th AVE EDMONTON, AB CA T6P 1P6 Contact: Melody Cui

Jonitact. Welduy Cui

melody.cui@cacindustrials.com

T: F:

Diagnosis

Confirm the source of the lubricant being utilized for top-up/fill. Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. Additive levels indicate the addition of a different brand, or type of oil. Viscosity of sample indicates oil is within SAE 80 range, advise investigate. The condition of the oil is acceptable for the time in service.

Depot:CAC241EDMUnique No:5620810Signed:Kevin MarsonReport Date:14 Aug 2023

LIEBHERR

CONSTRUCTION EQUIPMENT





GRAPHS

