

LIEBHERR

CONSTRUCTION EQUIPMENT



LIEBHERR LH50M 145461-1216 - Rear Left Wheel Hub

Sample No: LH0255611

Oil Type: GEAR OIL SAE 75W90



GENERAL RECYCLING INDUSTRIES LTD.
 4120 - 84 AVENUE
 EDMONTON, AB
 CA T6B 3H3
 Contact: Corey MacKay
 cmackay@trailco.ca
 T: (587)926-1610
 F: (780)485-4294



SAMPLE INFORMATION

Sample Number	LH0255611	---	---	---
Sample Date	26 Jun 2023	---	---	---
Machine Hours	1086	---	---	---
Oil Hours	0	---	---	---
Oil Changed	N/A	---	---	---
Sample Status	NORMAL	---	---	---



OIL CONDITION

Visc @ 40°C	cSt	● 102	---	---	---
-------------	-----	-------	-----	-----	-----



CONTAMINATION

Silicon	ppm	● 6	---	---	---
Sodium	ppm	● 2	---	---	---
Potassium	ppm	● 1	---	---	---



WEAR METALS

Iron	ppm	● 10	---	---	---
Copper	ppm	● 46	---	---	---
Lead	ppm	● 1	---	---	---
Tin	ppm	● 0	---	---	---
Aluminum	ppm	● <1	---	---	---
Chromium	ppm	● 0	---	---	---
Molybdenum	ppm	● 1	---	---	---
Nickel	ppm	● 0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	● <1	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	● 58	---	---	---
Magnesium	ppm	● 1	---	---	---
Zinc	ppm	● 42	---	---	---
Phosphorus	ppm	● 1358	---	---	---
Barium	ppm	● <1	---	---	---
Boron	ppm	● 258	---	---	---

Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 75W90. Please confirm.

All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: GEN156EDM
Unique No: 5629920
Signed: Wes Davis
Report Date: 18 Aug 2023



GRAPHS

