

LIEBHERR

CONSTRUCTION EQUIPMENT



092696 - Rear Left Wheel Hub

Sample No: LH0274566

Oil Type: PETRO CANADA TRAXON 75W90 SYNTHETIC



SAMPLE INFORMATION

Sample Number	LH0274566	LH0247219	LH0239180	LH
Sample Date	05 Sep 2023	06 Apr 2023	08 Sep 2022	27 Jul 2021
Machine Hours	13109	12387	11186	8788
Oil Hours	0	0	0	0
Oil Changed	Changed	Changed	Changed	Changed
Sample Status	NORMAL	NORMAL	NORMAL	NORMAL

American Iron and Metal

75 Steel City Court
Hamilton, ON
CA L8H 3Y2
Contact: Heavy Equipment
hamiltonmobileassetmaintenance@aim-recycling.com
T: (905)547-5533
F: (905)544-5671



OIL CONDITION

Visc @ 40°C	cSt	99.3	96.2	118	103



CONTAMINATION

Element	ppm	2	2	<1	1
Silicon	ppm	2	2	<1	1
Sodium	ppm	<1	<1	2	<1
Potassium	ppm	<1	1	<1	<1



WEAR METALS

Element	ppm	3	3	10	3
Iron	ppm	3	3	10	3
Copper	ppm	5	5	<1	4
Lead	ppm	0	<1	0	0
Tin	ppm	0	0	0	0
Aluminum	ppm	0	0	<1	0
Chromium	ppm	0	0	0	0
Molybdenum	ppm	0	0	0	0
Nickel	ppm	0	<1	<1	<1
Titanium	ppm	0	0	0	0
Silver	ppm	<1	0	0	<1
Manganese	ppm	0	0	<1	0
Vanadium	ppm	0	0	0	0



ADDITIVES

Element	ppm	8	9	4	9
Calcium	ppm	8	9	4	9
Magnesium	ppm	2	3	<1	1
Zinc	ppm	12	12	8	7
Phosphorus	ppm	1274	1351	849	1305
Barium	ppm	0	0	0	0
Boron	ppm	300	299	22	317

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: AMEHAM
Unique No: 5633852
Signed: Wes Davis
Report Date: 06 Sep 2023



GRAPHS

