## CONSTRUCTION EQUIPMENT

## LIEBHERR R954954R - Swing Drive

Sample No: LH0265883

Oil Type: PETRO CANADA TRAXON SYNTHETIC 75W90

-							
<b>J</b> SAMPLE INFORMATION							
Sample Number		LH0265883	LH0199530	LH0234375	LH0234374		
Sample Date		31 Aug 2023	14 Apr 2023	09 Mar 2023	09 Mar 2023		
Machine Hours		0	0	0	0		
Oil Hours		0	0	0	0		
Oil Changed		Changed	Changed	Changed	Changed		
Sample Status		NORMAL	NORMAL	ABNORMAL	NORMAL		
Visc @ 40°C	cSt	0 105	0 108	96.2	86.0		
Silicon	ppm	6	3	0 11	3		
Sodium	ppm	01	○ <1	3	○ <1		
Potassium	ppm	<b>○</b> <1	01	○ <1	○ <1		

WEAR METALS						
PQ				0 16		
Iron	ppm	<b>572</b>	0 112	0 1120	0 12	
Copper	ppm	0 72	22	0 199	◯ <1	
Lead	ppm	<b>4</b>	○ <1	6	0	
Tin	ppm	01	◯ <1	3	0	
Aluminum	ppm	<b>○</b> <1	○ <1	2	○ <1	
Chromium	ppm	<b>3</b>	○ <1	6	0	
Molybdenum	ppm	01	○ <1	2	0	
Nickel	ppm	01	◯ <1	2	0	
Titanium	ppm	0	0	<1	0	
Silver	ppm	0	0	0	0	
Manganese	ppm	<b>3</b>	○ <1	8	○ <1	
Vanadium	ppm	0	0	0	0	

0 **ADDITIVES** 26 Calcium ppm 0 10 35 22 Magnesium 0 13  $\bigcirc 5$ 29 6 ppm Zinc 0 36 011 0 67 0 135 ppm Phosphorus ppm 0 1103 0 1163 0 1286 0 1107 Barium 0 ppm  $\bigcirc 0$  $\bigcirc 0$  $\bigcirc 0$ Boron ppm 89 0 149 0 183 0 171





Gerdau - Mandak Metal Processors Ltd., 1 Railway St., P.O. Box 334 Selkirk, MB CA R1A 2B3 Contact: Santiago Giraldo santiago.giraldo@gerdau.com T: F: (204)482-8241

## Diagnosis

Confirm the source of the lubricant being utilized for top-up/fill. Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. Additive levels indicate the addition of a different brand, or type of oil. The condition of the oil is acceptable for the time in service.

Depot:	MANSEL
Unique No:	5642543
Signed:	Wes Davis
Report Date:	11 Sep 2023

Contact/Location: Santiago Giraldo - MANSEL

## **CONSTRUCTION EQUIPMENT**



GRAPHS

 $\overline{\mathbf{O}}$ 

