LIEBHERR

CONSTRUCTION EQUIPMENT



[(349195)] LIEBHERR L556 062539-1757 - Splitter Box

Sample No: LH0265633

Oil Type: PETRO CANADA TRAXON 75W90 SYNTHETIC

5					
SAM	PLE INFO	RMATION			
Sample Number		LH0265633	LH0221718	LH0246997	LH0223886
Sample Date		27 Jul 2023	11 May 2023	06 Mar 2023	26 Oct 2022
Machine Hours		9190	8000	7539	6161
Oil Hours		0	0	0	0
Oil Changed		Changed	Changed	Changed	Changed
Sample Status		NORMAL	NORMAL	NORMAL	NORMAL
OILC	ONDITIO	N			
/isc @ 40°C	cSt	86.8	○ 89.0	○ 83.5	O 95.3
CON	TAMINA	TION			
Silicon	ppm	2	O 1	O 2	O 2
Sodium	ppm	○ <1	O <1	O <1	O 1
Potassium	ppm	 <1	0	O <1	O 0
ron	ppm	12	O 7	O 11	O 13
Copper	ppm	○ <1	O <1	O <1	O <1
_ead	ppm	1	O <1	O <1	<1
Γin	ppm	0	O 0	O 0	0
Aluminum	ppm	○ <1	 <1	<1	O <1
Chromium	ppm	1	 <1	O <1	<1
Molybdenum	ppm	0	0	O 0	O 0
Vickel	ppm	0	0	O <1	0
Titanium	ppm	0	0	0	0
Silver	ppm	0	0	0	0
Manganese	ppm	0 0	0	O 0	O <1
/anadium	ppm	0	0	0	0
ADD	ITIVES				
Calcium	ppm	117	O 77	58	45
Magnesium	ppm	2	0 2	 <1	O <1
Zinc	ppm	156	O 71	O 52	37
Phosphorus	ppm	1288	O 1292	901	O 1384
Barium	ppm	0	O 0	O 0	O 0

272

56

270



Eacom Timber Corporation 100 Old Nairn Centre Road Nairn Centre, ON CA POM 2L0 Contact: Service Manager

T: F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: EACNAl
Unique No: 5643258
Signed: Wes Davis
Report Date: 14 Sep 2023

258

ppm


Boron

CONSTRUCTION EQUIPMENT





GRAPHS



Report Id: EACNAI [WCAMIS] 02582193 (Generated: 09/15/2023 12:34:36) Rev: 1

Submitted By: ?