



## LIEBHERR L556 065678-1826 - Rear Right Wheel Hub

Sample No: LH0232599

Oil Type: GEAR OIL SAE 80W90

## **SAMPLE INFORMATION**

Sample Number	LH0232599	LH	 
Sample Date	31 Jul 2023	26 Apr 2023	 
Machine Hours	3914	3418	 
Oil Hours	0	0	 
Oil Changed	Changed	N/A	 
Sample Status	NORMAL	ABNORMAL	 

OIL CONDITION						٦ F
:@ 40°C	cSt	185	95.1			

Silicon	ppm	02	0 17				
Sodium	ppm	◯ <1	03				
Potassium	ppm	◯ <1	0 ()				

-			<u> </u>	
WEA WEA	<b>AR META</b>	LS		
PQ			0 147	 
	10.10.000		<u> </u>	
Iron	ppm	0 45	0 562	 
Copper	ppm	0 32	0 203	 
Lead	ppm	<b>○</b> <1	0 5	 
Tin	ppm	1	0 12	 
Aluminum	ppm	0	○ <1	 
Chromium	ppm	<b>○</b> <1	2	 
Molybdenum	ppm	0	0	 
Nickel	ppm	◯ <1	03	 
Titanium	ppm	0	0	 
Silver	ppm	0	0	 
Manganese	ppm	0 2	14	 
Vanadium	ppm	0	0	 

0

Visc

	TIVES			
Calcium	ppm	07	36	 
Magnesium	ppm	<b>○</b> <1	2	 
Zinc	ppm	0 17	70	 
Phosphorus	ppm	0 2352	2735	 
Barium	ppm	0	0	 
Boron	ppm	0 21	223	 

BOIS LIB INC.

275 RUE JEREMIE-PACAUD PRINCEVILLE, QC CA G6L 0A1 Contact: Service Manager

T: F:

### Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 80W90. Please confirm.

All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:LIBPRIUnique No:564364Signed:Wes Date:Report Date:14 Sep

LIBPRI 5643648 Wes Davis 14 Sep 2023

# CONSTRUCTION EQUIPMENT



GRAPHS

 $\overline{\mathbf{O}}$ 

