



LIEBHERR L556 065678-1826 - Front Right Wheel Hub

Sample No: LH0232597

Oil Type: **GEAR OIL SAE 80W90**

_					
SAMPLE INFORMATION					
Sample Number	LH0232597	LH			
Sample Date	31 Jul 2023	26 Apr 2023			
Machine Hours	3914	3418			
Oil Hours	0	0			
Oil Changed	Changed	N/A			
Sample Status	NORMAL	SEVERE			
<u> </u>					
OIL CONDI	TION				
Vian @ 400C	O 107	07.0	i i		



BOIS LIB INC.

275 RUE JEREMIE-PACAUD PRINCEVILLE, QC CA G6L 0A1

Contact: Service Manager

T:

F:

Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 80W90. Please confirm.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Visc @ 40°C	cSt	187	97.2			
**						
CONTAMINATION						
Silicon	ppm	3	O 21			
Sodium	ppm	○ <1	5			
Potassium	ppm	0	O 0			
WEAR METALS						
PQ			O 129			
Iron	ppm	56	625			

W EA	R ME I ALS			
PQ			O 129	
Iron	ppm	56	O 625	
Copper	ppm	67	282	
Lead	ppm	2	0 8	
Tin	ppm	3	<u>24</u>	
Aluminum	ppm	0 <1	O 2	
Chromium	ppm	() <1	○ 3	
Molybdenum	ppm	0	0	
Nickel	ppm	1	<u> </u>	
Titanium	ppm	0	0	
Silver	ppm	0	0	
Manganese	ppm	2	26	
Vanadium	ppm	0	0	

variadium	ppiii	U	U			
ADDITIVES						
Calcium	ppm	3	10			
Magnesium	ppm	0 <1	2			
Zinc	ppm	21	125			
Phosphorus	ppm	2410	3162			
Barium	ppm	0	0			
Boron	ppm	14	207			

Depot: LIBPRI **Unique No:** 5643668 Signed: Kevin Marson **Report Date:** 15 Sep 2023

LIEBHERR

CONSTRUCTION EQUIPMENT





GRAPHS

