LIEBHERR





[TECHNICORE] 116005 - Splitter Box

Sample No: LH0270487

Oil Type: PETRO CANADA TRAXON 75W90 SYNTHETIC

SAM	PLE INFO	RMATION		
Sample Number		LH0270487	 	
Sample Date		27 Sep 2023	 	
Machine Hours		7090	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
<u> </u>				
OILC	ONDITIO	N		
Visc @ 40°C	cSt	89.5		
VISC @ 40 C	COL	09.5	 	
CON	TAMINA	FION		
Silicon	ppm	() <1	 	
Sodium	ppm	0 1	 	
Potassium	ppm	0	 	
◎ WEA	R METAL	C		
	R ME I AL			
lron	ppm	8	 	
Copper	ppm	1	 	
Lead	ppm	() <1	 	
Tin	ppm	0	 	
Aluminum	ppm	() <1	 	
Chromium	ppm	0	 	
Molybdenum	ppm	0	 	
Nickel	ppm	○ <1	 	
Titanium	ppm	0	 	
Silver	ppm	<1	 	
Manganese	ppm	0	 	
Vanadium	ppm	0	 	
ADDI	ITIVES			
Calcium	ppm	19	 	
Magnesium	ppm	O 12	 	
Zinc	ppm	O 41	 	
Phosphorus	ppm	O 1188	 	
Barium	ppm	O <1	 	
Boron	ppm	O 285	 	
Doron	ppiii	_ 203		

LIEBHERR CANADA LTD.

1015 SUTTON DRIVE BURLINGTON, ON CA L7L 5Z8

Contact: Joseph Gillis joseph.gillis@liebherr.com

T:

F: (905)319-6622

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:LIEMISUnique No:5656292Signed:Wes DavisReport Date:05 Oct 2023

LIEBHERR

CONSTRUCTION EQUIPMENT





GRAPHS

