LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR LH50 37429 - Diesel Engine

Sample No: LH0277650

Silicon

Sodium

Potassium

ppm

ppm

ppm

6

2

1

Oil Type: DIESEL ENGINE OIL SAE 40



Visc @ 100°C	cSt	13.0					
Oxidation (PA)	%	71					
CONT	AMINATIO	AN					
CONI	AMINAIN						
Soot %	%	0					
Nitration (PA)	%	71					
Sulfation (PA)	%	55					
Glycol	%	NEG					
Fuel	%	<1.0					

WEAR METALS							
Iron	ppm	3					
Copper	ppm	2					
Lead	ppm	() <1					
Tin	ppm	0					
Aluminum	ppm	1					
Chromium	ppm	0					
Molybdenum	ppm	60					
Nickel	ppm	0					
Titanium	ppm	0					
Silver	ppm	0 <1					
Manganese	ppm	0					
Vanadium	ppm	0					

ADDITIVES						
Calcium	ppm	1075				
Magnesium	ppm	982				
Zinc	ppm	1217				
Phosphorus	ppm	990				
Barium	ppm	 <1				
Boron	ppm	3				





LIEBHERR CANADA LTD.

1015 SUTTON DRIVE BURLINGTON, ON CA L7L 5Z8

Contact: Joseph Rodgers joseph.rodgers@liebherr.com

T: (905)319-9222 F: (905)319-6622

Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) DIESEL ENGINE OIL SAE 40. Please confirm.

All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:LIEMISUnique No:5657954Signed:Wes DavisReport Date:13 Oct 2023

LIEBHERR





GRAPHS

